F10 Effect of tool idle time (P2 K2)



Same arrivals and tasks; only the delay between steps changes. Thin lines: individual repeats (paired task mixes); thick line: mean.