

has a loaver

major level = \$2,795

Standard Probe Incoming Inspection Form

Customer / Probe Information

Internal Work Order (If Internal)	Model#	GE ICS-9-D-2	
Sales Order# 365248	Customer	Ascension Genesis Hospital	Bin# 234
Work Order# 341463	Serial	1415721Wx8	

Customer Complaint: intermittent imaging issue Technician: VE Date: 6/25/26

Disinfected Probe?

☒ Yes

☐ No

Visual Inspection Test (Must disinfect transducer prior to inspection)

Lens/Dome

- ☒ No Damage
- ☐ Dirty
- ☐ Discolored
- ☐ Dented / Chipped
- ☐ Peeling / Delaminated
- ☐ Scratched
- ☐ Cut in Membrane
- ☐ Holes / Pin Holes
- ☐ Separated from Housing
- ☐ Dome Leaking Oil
- ☐ Other/Comments:

Cable

- ☒ No Damage
- ☐ Dirty
- ☐ Discolored or Stained
- ☐ Abrasions
- ☐ Cut or Torn
- ☐ Twisted
- ☐ Stiff
- ☐ Pulled out from Strain Relief
- ☐ Ink
- ☐ Other/Comments:
- ☐ Measure Cable (Strain to Strain) _____

Housing/Handle

- ☒ No Damage
- ☐ Dirty
- ☐ Scratched
- ☐ Stained
- ☐ Crack (s)
- ☐ Dent (s)
- ☐ Gaps in Seal
- ☐ Leaking Oil
- ☐ Previous Refurbishment
- ☐ Other/Comments:

Connector Strain

- ☒ No Damage
- ☐ Dirty
- ☐ Discolored or Stained
- ☐ Cut or Torn
- ☐ Peeling
- ☐ Separated from Connector
- ☐ Other/Comments:

Housing Strain

- ☒ No Damage
- ☐ Dirty
- ☐ Discolored or Stained
- ☐ Ink
- ☐ Cut or Torn
- ☐ Peeling
- ☐ Separated from Housing
- ☐ Other/Comments:

Connector

- ☒ No Damage
- ☐ Dirty / Scratched / Stained
- ☐ Paint Chipped
- ☐ Cracked
- ☐ Dented
- ☐ Missing Screws
- ☐ Locking Knob or Pin Broken/Missing
- ☐ Connector Pins Broken / Bent / Missing
- ☐ Connector Module Broken
- ☐ Corrosion/Evidence of Fluid
- ☐ Tamper Sticker: _____
- ☐ Other/Comments:

Standard Probe Incoming Test Summary

TEST	PASS	FAIL	N/A	RESULTS/COMMENTS
Visual Inspection	☒	☐	☐	
Sensitivity Test	☐	☒	☐	Dropout
Impedance/Capacitance Test	☐	☒	☐	
Leakage Test	☒	☐	☐	5.6
System Scan Test	Test Bed Used: <u>Logic 994</u>			☐ No System Verify/Initial: _____
2D Image	☐	☒	☐	Dropout
Color Mode	☐	☒	☐	cobrasee started by self constantly through the test on both test
CW Mode	☐	☐	☒	
3D/4D	☐	☐	☒	

Complaint Confirmed? ☒ Yes ☐ No ☐ Needs More Information
 Is there evidence of Customer Abuse? ☐ Yes ☐ No ☒ Cannot Be Determined

Diagnostic Findings: Damage to Array & cable
Check boards.

Pre-quote repairs completed: _____ Tech: _____ Time: _____

Quote Decision

☒ Quote Customer Repair ☐ No Repairs Needed ☐ Not Repairable Mgr Sign Off: _____

Required and Optional Repairs:

Repair Turn Time: ☒ 10 Days ☐ Other _____ days

Req	Opt	Repair
☐	☐	Array Repair
☒	☐	Cable & Array Replacement
☐	☐	3D/4D Fluid Recharge
☐	☐	3D/4D Dome Replacement
☐	☐	3D/4D Motor Repair
☐	☐	Cable Patch
☐	☐	Cable Reattachment
☐	☐	Cable Refurb
☐	☐	Cable Replacement
☐	☐	Cable Whitening
☐	☐	Connector Refurb
☐	☐	Connector Housing Replacement
☐	☐	Connector Module Replacement
☐	☐	CW Noise Reduction
☐	☐	Electrical Board Repair

Req	Opt	Repair
☐	☐	Housing Rebuild
☐	☐	Housing Refurb
☐	☐	Housing Reseal
☐	☐	Knob or Locking Pin Replacement
☐	☐	Lens Refurb
☐	☐	Lens Replacement
☐	☐	Lens Reseal
☐	☐	Paint Connector
☐	☐	Pin Replacement / Repair
☐	☐	Retermination
☐	☐	Strain Relief Reattachment
☐	☐	Strain Relief Refurb
☐	☐	Strain Relief Replacement
☐	☐	Other (see notes)

Hot Swap Option Available? ☐ Yes ☒ No Reason: _____
 Has the Ops Team reviewed all documentation? ☐ Yes ☒ No Initial: U

Notes: _____