Stage 4: Support for all DP opcodes

As stated in the overview, this stage does not require any additional hardware design, assuming that the ALU designed in stage 1 already supports all DP opcodes. Therefore, the task at this stage is simply to test the design of stage 3 extensively, covering all DP instructions. Small assembly programs including various DP instructions may be constructed and run on the circuit designed. This is also a time to catch up on any thing pending in the previous designs.