Manufacturing of modules: Glued HDI on BBM			
Procedure performed according to SOP 105-v0			
Date: 1/29/2016		Finish time: 29/1/2016-17:49:38	
Start time: 29/1/2016-16:45:27		pressure: 89.5	
operator: Jmonroy		Sylgard batch no.: 8092903	
Software version: dev			
Object status updated in Purdue database (Justify in comments): yes			
List id of parts involved in table below: UNL batch(es) No. :na			
Chuck2	Chuck 3		
M-H-1-29	M-H-1-43		
M-G-2-26	M-H-2-26		
Special observations and comments:			
Orientation:			
Encapsulation:			

Others: