Manufacturing of modules: Glued HDI on BBM		
Procedure performed according to SOP 103-v0		
Date: 7/3/2016		Finish time: 3/7/2016-09:07:30
Start time: 3/7/2016-08:29:20		pressure: 69
operator: Jmonroy		Araldite batch no. : ADE0254200
Software version: dev		
Object status updated in Purdue database (Justify in comments): yes		
List id of parts involved in table below: Chuck No. :2		
BBM ID	HDI S/N	
BL FR 335	YHH46-0216-2-40	
BL BB 335	YHH51-0216-2-40	
	1111131-0210-2-40	
Special observations and comments:		
Orientation:		
Glueing:		
Pick&place:		
Weight:		
Others:		