INTRODUCTION


STEPS FOR MODELLING

1. Create a sketch
   - Specify a plane/face
   - Create geometry
   - Dimension geometry


2. Create feature
   A feature can be created using Extrude, Revolve or Sweep

Creating a model file and Specifying file path;

- Launch the NX program.
- Click on New in the file menu as shown below.



- A new dialogue box appears. Make sure the model template is selected as below.



- Enter the name of the file as required by the chapter.
- Specify the file path as required by the chapter.


NB: All files will be saved in a folder on the Desktop (C:\Users\%UserName%\Desktop\)

The folder should be named as “ME473tutorials”


<u>Creating a Sketch;</u>

Each model begins with a sketch, so it is very important that you know how to create sketches in the appropriate plane.

- Select insert from the menu bar, then click on “Sketch in Task Environment.”



- Select the appropriate plane for the sketch as shown below



- The sketch environment is generated in the specified plane.
- Now the sketch tools will be available to you to create the sketch required.
- After creating the sketch/geometry, exit out of the sketch environment with the finish sketch command

TRY

Try to explore placing sketches in various planes as offered by the 3D environment. Familiarize yourself with the planes and figure out which give you the right orientation of the model you want to create.