

Tutorial 12;


- Create a sketch plane




- Reproduce the exact sketch below




- Extrude the sketch as shown




- The resulting part should be as shown




- Create the sketch below in the required plane



- Extrude to attain the result below




- Fix a rectangular pad to the end face, using the dimensions shown below




- Use the next two diagrams to position the pad accordingly


- Horizontally




- Vertically




- Create another pad on the end as shown




- Use the parameters below to specify the pad




- Position the pad as shown below




- Blend the edges of the newly created pad as shown




- Create cylindrical pocket as specified below




- Use the point-to-point to place it in position as shown




- Create a sketch profile on the top face of the part as shown



- Reproduce the exact sketch shown below



- Extrude the sketch using the parameters specified below



ASSIGNMENT 12

