

X1 X2X3X4X5X6X7X8X9X10

Y1 Y2Y3Y4Y5Y6Y7Y8Y9Y10

MD100H Ver1.0

VO

S10

S9

S8

S7

S6

S5

S4

S3

S2

S1

12V Y 0V IN

24V 5V 0V IR_L IR_H

5V 0V A2 B2

5V 0V 2R 2T UR UT A1 B1

T_24

GND

T_5V

T_3V3