

Raspberry Pi watchdog: no new command `seq` for 1 s ⇒ pulses switched off ⇒ Uno enters FAIL-SAFE.
Ground station: "ARM" sends yaw 0 / throttle 0, then yaw 50 after 1.2 s; "DISARM" sends yaw 100 / throttle 0.