Thursday, March 5, 2020 2:00:19 PM

90951	1637	Install Lane Memory	Assigned BB
90927	1644	Install Lane Memory	Assigned BB
91626	1632	Music box not working	Assigned BG
91581	1652	Attend Construction meeting	Assigned CS
91099	1616	Replace Secondary POS Controller	Assigned CS
91100	1638	Replace Primary POS Controller	Assigned CS
91414	59120	Update assett lists for VOIP Routers	Assigned CS
91415	1587	Update Assett list - add Pharmacy	Assigned CS
91434	1652	Move network connections to UPS	Assigned CS
91571	1652	Re-install 4 SCOT lanes	Assigned CS
91572	1652	Install 2 SCOT lanes	Assigned CS
91580	1652	image Pharmacy lane with POS Ready 7 image	Assigned CS
91665	1598	Replace POS lane from a 7459 to a 7606	Assigned CS
91661	1631	Move devices to replacement switch - verify	Assigned CS
91664	1598	Replace Secondary POS Controller	Assigned CS
91663	1598	Replace VOIP Router	Assigned CS
91573	1652	re-install RAP Station and Rap lane	Assigned CS
91662	1638	Replace hand-scanner at the Service Desk	Assigned CS
91653	1652	Multiple SCOT lane issues	Assigned CS
91660	1658	Verify Pharmacy holders for Pharmacy PC scanners	Assigned CS
91659	1587	Test payment terminals for new Pharmacy POS lanes	Assigned CS
91658	1587	Install additional Access point	Assigned CS
91657	1587	Work with Pharmacy to test Pharmacy equipment	Assigned CS
91656	1587	Set-up Catalina for POS lane 4	Assigned CS
91655	1652	Set-up Catalina for 2 additional SCOT lanes	Assigned CS
90947	1603	Install Lane Memory	Assigned JB
90937	1649	Install Lane Memory	Assigned JB
90930	1634	Install Lane Memory	Assigned JB

04247 4045	1121	A I ID
91347 1915	Line 3 not working	Assigned JB