Monday, March 2, 2020 2:44:57 PM

90927	1644	Install Lane Memory	Assigned BB
90930	1634	Install Lane Memory	Assigned JB
90937	1649	Install Lane Memory	Assigned JB
90947	1603	Install Lane Memory	Assigned JB
90951	1637	Install Lane Memory	Assigned BB
91099	1616	Replace Secondary POS Controller	Assigned CS
91100	1638	Replace Primary POS Controller	Assigned CS
91347	1915	Line 3 not working	Assigned JB
91414	59120	Update assett lists for VOIP Routers	Assigned CS
91415	1587	Update Assett list - add Pharmacy	Assigned CS
91434	1652	Move network connections to UPS	Assigned CS
91571	1652	Re-install 4 SCOT lanes	Assigned CS
91572	1652	Install 2 SCOT lanes	Assigned CS
91573	1652	re-install RAP Station and Rap lane	Assigned CS
91580	1652	image Pharmacy lane with POS Ready 7 image	Assigned CS
91581	1652	Attend Construction meeting	Assigned CS
91626	1632	Music box not working	Assigned BG