

Network Incident Investigation Report

Dynamic RCA & Timeline Reconstruction Analysis

Total Reconstructed Incidents:	115	Total Analyzed Log Events:	398
Investigation Date:	2026-06-29	Analyzed Log Sources:	192.168.1.10, 192.168.1.104, 9300, Access-6100-01, Access-6100-02, Access-6100-03, Access-6100-04, Access-6100-05, Core-8325-01, Dist-6300-01, Edge-6300-01, leaf1, router-1, router-2

Incident Overview Table

Incident ID	Start Time	End Time	Duration	Event Count	Affected Devices
WORKFLO W-0001	2026-04-07T08:20:39	2026-04-07T08:20:39	0.2s	41	9300
WORKFLO W-0002	2026-05-14T14:00:02	2026-05-14T14:02:11	2.1m	3	192.168.1.10, 192.168.1.104
WORKFLO W-0003	2026-05-14T14:00:49	2026-05-14T14:00:49	0.0s	1	router-1
WORKFLO W-0004	2026-05-14T14:05:01	2026-05-14T14:05:01	0.0s	1	192.168.1.10
WORKFLO W-0005	2026-05-14T14:05:01	2026-05-14T14:10:15	5.2m	4	192.168.1.10, 192.168.1.104, router-1
WORKFLO W-0006	2026-05-14T14:10:02	2026-05-14T14:10:02	0.0s	1	192.168.1.104
INC-0007	2026-05-14T14:15:01	2026-05-14T14:15:01	0.0s	2	192.168.1.10, 192.168.1.104
INC-0008	2026-05-14T14:18:47	2026-05-14T14:19:51	1.1m	5	192.168.1.10
INC-0009	2026-05-14T14:20:15	2026-05-14T14:22:40	2.4m	5	192.168.1.10, 192.168.1.104
WORKFLO W-0010	2026-05-14T14:25:11	2026-05-14T14:25:11	0.0s	1	192.168.1.104
WORKFLO W-0011	2026-05-14T14:30:45	2026-05-14T14:30:45	0.0s	1	192.168.1.104
WORKFLO W-0012	2026-05-14T14:31:12	2026-05-14T14:31:12	0.0s	1	192.168.1.104
INC-0013	2026-05-14T14:32:01	2026-05-14T14:32:01	0.0s	1	192.168.1.104
INC-0014	2026-05-14T14:35:19	2026-05-14T14:43:10	7.8m	5	192.168.1.10, 192.168.1.104
INC-0015	2026-05-14T14:35:19	2026-05-14T14:35:19	0.0s	1	192.168.1.104

WORKFLO W-0016	2026-05-14T14:42:33	2026-05-14T14:50:00	7.5m	3	192.168.1.10, 192.168.1.104, router-1
INC-0017	2026-05-14T14:51:15	2026-05-14T14:54:30	3.2m	13	192.168.1.10, 192.168.1.104, router-1
WORKFLO W-0018	2026-05-14T14:55:01	2026-05-14T14:55:01	0.0s	1	192.168.1.104
WORKFLO W-0019	2026-05-14T15:03:20	2026-05-14T15:04:22	1.0m	4	192.168.1.10, router-1
INC-0020	2026-05-14T15:04:12	2026-05-14T15:04:14	2.0s	2	router-1
WORKFLO W-0021	2026-05-20T09:00:05	2026-05-20T09:00:05	0.0s	1	192.168.1.10
WORKFLO W-0022	2026-05-20T09:01:12	2026-05-20T09:02:15	1.1m	4	192.168.1.10, router-2
WORKFLO W-0023	2026-05-20T09:05:30	2026-05-20T09:05:30	0.0s	1	192.168.1.10
WORKFLO W-0024	2026-05-20T09:08:01	2026-05-20T09:08:01	0.0s	1	192.168.1.10
INC-0025	2026-05-20T09:12:44	2026-05-20T09:12:44	0.0s	1	192.168.1.10
WORKFLO W-0026	2026-05-20T09:14:00	2026-05-20T09:14:35	35.0s	2	192.168.1.10
WORKFLO W-0027	2026-05-20T09:18:00	2026-05-20T09:20:10	2.2m	2	192.168.1.10, router-2
INC-0028	2026-05-20T09:25:00	2026-05-20T09:31:00	6.0m	17	192.168.1.10, router-2
WORKFLO W-0029	2026-05-20T09:33:00	2026-05-20T09:33:00	0.0s	1	192.168.1.10
INC-0030	2026-05-20T09:35:10	2026-05-20T09:43:01	7.8m	7	192.168.1.10, router-2
INC-0031	2026-05-20T09:50:00	2026-05-20T09:55:20	5.3m	7	192.168.1.10, router-2

WORKFLO W-0032	2026-05-20T10:02:10	2026-05-20T10:02:10	0.0s	1	192.168.1.10
INC-0033	2026-05-20T10:05:00	2026-05-20T10:05:40	40.0s	3	192.168.1.10
INC-0034	2026-05-20T10:10:00	2026-05-20T10:10:00	0.0s	1	router-2
WORKFLO W-0035	2026-05-20T10:20:00	2026-05-20T10:20:00	0.0s	1	router-2
INC-0036	2026-05-21T10:00:05	2026-05-21T10:00:08	3.0s	4	Dist-6300-01
WORKFLO W-0037	2026-05-21T10:00:12	2026-05-21T10:01:00	48.0s	2	Core-8325-01
INC-0038	2026-05-21T10:00:23	2026-05-21T10:00:26	3.0s	2	Access-6100-02
INC-0039	2026-05-21T10:00:35	2026-05-21T10:00:44	9.0s	4	Core-8325-01
WORKFLO W-0040	2026-05-21T10:00:50	2026-05-21T10:00:50	0.0s	1	Access-6100-03
WORKFLO W-0041	2026-05-21T10:00:55	2026-05-21T10:00:55	0.0s	1	Dist-6300-01
WORKFLO W-0042	2026-05-22T11:00:10	2026-05-22T11:00:10	0.0s	1	192.168.1.10
WORKFLO W-0043	2026-05-22T11:05:00	2026-05-22T11:05:00	0.0s	1	192.168.1.10
INC-0044	2026-05-22T11:10:42	2026-05-22T11:11:55	1.2m	5	192.168.1.10
INC-0045	2026-05-22T11:18:00	2026-05-22T11:18:00	0.0s	1	192.168.1.10
INC-0046	2026-05-22T11:25:10	2026-05-22T11:25:38	28.0s	4	192.168.1.10
WORKFLO W-0047	2026-05-22T11:30:00	2026-05-22T11:30:00	0.0s	1	192.168.1.10
WORKFLO W-0048	2026-05-22T11:30:05	2026-05-22T11:30:05	0.0s	1	192.168.1.10
WORKFLO W-0049	2026-05-22T11:40:00	2026-05-22T11:40:00	0.0s	1	192.168.1.10
WORKFLO W-0050	2026-05-25T10:00:01	2026-05-25T10:00:01	0.0s	1	Core-8325-01

INC-0051	2026-05-25T10:01:05	2026-05-25T10:05:06	4.0m	7	Dist-6300-01
INC-0052	2026-05-25T10:02:10	2026-05-25T10:02:25	15.0s	4	Core-8325-01
INC-0053	2026-05-25T10:03:00	2026-05-25T10:03:08	8.0s	2	Access-6100-02
INC-0054	2026-05-25T10:04:15	2026-05-25T10:04:40	25.0s	4	Core-8325-01
WORKFLO W-0055	2026-05-25T10:06:00	2026-05-25T10:06:00	0.0s	1	Core-8325-01
WORKFLO W-0056	2026-06-02T08:00:05	2026-06-02T08:05:30	5.4m	6	192.168.1.10, router-1
WORKFLO W-0057	2026-06-02T08:08:01	2026-06-02T08:08:01	0.0s	1	192.168.1.10
WORKFLO W-0058	2026-06-02T08:10:00	2026-06-02T08:10:00	0.0s	1	router-1
INC-0059	2026-06-02T08:12:44	2026-06-02T08:20:10	7.4m	5	192.168.1.10, router-1
INC-0060	2026-06-02T08:25:00	2026-06-02T08:30:05	5.1m	12	192.168.1.10, router-1
WORKFLO W-0061	2026-06-02T08:33:00	2026-06-02T08:33:00	0.0s	1	192.168.1.10
INC-0062	2026-06-02T08:35:10	2026-06-02T08:35:10	0.0s	1	192.168.1.10
INC-0063	2026-06-02T08:38:00	2026-06-02T08:38:00	0.0s	1	192.168.1.10
INC-0064	2026-06-02T08:45:00	2026-06-02T08:45:00	0.0s	1	router-1
WORKFLO W-0065	2026-06-02T08:50:00	2026-06-02T08:50:00	0.0s	1	192.168.1.10
INC-0066	2026-06-02T08:50:12	2026-06-02T08:50:14	2.0s	2	router-1
WORKFLO W-0067	2026-06-02T08:50:20	2026-06-02T08:50:20	0.0s	1	192.168.1.10
WORKFLO W-0068	2026-06-02T08:50:45	2026-06-02T08:55:00	4.2m	4	192.168.1.10, router-1
WORKFLO W-0069	2026-06-02T09:00:00	2026-06-02T09:00:00	0.0s	1	router-1

WORKFLO W-0070	2026-06-02T09:02:10	2026-06-02T09:02:10	0.0s	1	192.168.1.10
INC-0071	2026-06-02T09:10:00	2026-06-02T09:12:00	2.0m	6	192.168.1.10
INC-0072	2026-06-02T09:15:00	2026-06-02T09:15:00	0.0s	1	router-1
WORKFLO W-0073	2026-06-02T09:18:00	2026-06-02T09:18:00	0.0s	1	192.168.1.10
WORKFLO W-0074	2026-06-02T09:18:15	2026-06-02T09:18:15	0.0s	1	192.168.1.10
WORKFLO W-0075	2026-06-02T09:18:40	2026-06-02T09:19:00	20.0s	2	192.168.1.10
INC-0076	2026-06-02T09:30:12	2026-06-02T09:31:00	48.0s	7	192.168.1.10
WORKFLO W-0077	2026-06-02T09:42:30	2026-06-02T09:42:30	0.0s	1	192.168.1.10
WORKFLO W-0078	2026-06-02T09:43:01	2026-06-02T09:43:01	0.0s	1	192.168.1.10
INC-0079	2026-06-02T10:05:00	2026-06-02T10:05:40	40.0s	3	192.168.1.10
WORKFLO W-0080	2026-06-02T10:30:00	2026-06-02T10:30:00	0.0s	1	192.168.1.10
INC-0081	2026-06-18T09:10:01	2026-06-18T09:10:10	9.0s	9	192.168.1.104
WORKFLO W-0082	2026-06-18T12:28:41	2026-06-18T12:28:41	0.2s	13	leaf1
INC-0083	2026-06-18T17:31:01	2026-06-18T17:31:01	0.0s	7	Edge-6300-01
WORKFLO W-0084	2026-07-12T09:00:01	2026-07-12T09:00:03	2.1s	2	Core-8325-01
WORKFLO W-0085	2026-07-12T09:01:15	2026-07-12T09:01:15	0.0s	1	Core-8325-01
INC-0086	2026-07-12T09:05:12	2026-07-12T09:05:21	8.6s	10	Dist-6300-01
INC-0087	2026-07-12T09:10:02	2026-07-12T09:10:08	6.0s	2	Access-6100-04
INC-0088	2026-07-12T09:15:11	2026-07-12T09:15:25	14.4s	4	Core-8325-01
INC-0089	2026-07-12T09:18:10	2026-07-12T09:18:16	6.0s	2	Core-8325-01

WORKFLO W-0090	2026-07-12T09:22:00	2026-07-12T09:22:06	5.9s	7	Dist-6300-01
WORKFLO W-0091	2026-07-12T09:25:15	2026-07-12T09:25:15	0.0s	1	Core-8325-01
WORKFLO W-0092	2026-07-12T09:25:18	2026-07-12T09:25:18	0.0s	1	Core-8325-01
WORKFLO W-0093	2026-08-15T10:00:01	2026-08-15T10:00:01	0.0s	1	Core-8325-01
WORKFLO W-0094	2026-08-15T10:00:03	2026-08-15T10:00:03	0.0s	1	Core-8325-01
INC-0095	2026-08-15T10:01:10	2026-08-15T10:04:10	3.0m	16	Core-8325-01, Dist-6300-01
INC-0096	2026-08-15T10:01:14	2026-08-15T10:01:18	4.1s	2	Access-6100-03
INC-0097	2026-08-15T10:01:20	2026-08-15T10:01:25	5.1s	2	Core-8325-01
INC-0098	2026-08-15T10:02:10	2026-08-15T10:02:22	12.2s	5	Core-8325-01
INC-0099	2026-08-15T10:03:08	2026-08-15T10:03:20	12.7s	4	Access-6100-05
WORKFLO W-0100	2026-08-15T10:05:01	2026-08-15T10:05:01	0.0s	1	Core-8325-01
WORKFLO W-0101	2026-08-15T10:05:04	2026-08-15T10:05:10	5.3s	2	Core-8325-01
WORKFLO W-0102	2026-08-15T10:05:20	2026-08-15T10:05:20	0.0s	1	Core-8325-01
WORKFLO W-0103	2026-09-01T10:00:01	2026-09-01T10:04:55	4.9m	4	Core-8325-01
INC-0104	2026-09-01T10:00:09	2026-09-01T10:04:10	4.0m	20	Core-8325-01, Dist-6300-01
WORKFLO W-0105	2026-09-01T10:00:05	2026-09-01T10:04:30	4.4m	3	Core-8325-01
WORKFLO W-0106	2026-09-01T10:00:08	2026-09-01T10:04:40	4.5m	2	Access-6100-01
INC-0107	2026-09-01T10:01:22	2026-09-01T10:01:26	4.0s	2	Core-8325-01

INC-0108	2026-09-01T10:02:00	2026-09-01T10:02:06	6.0s	2	Access-6100-02
INC-0109	2026-09-01T10:02:15	2026-09-01T10:02:27	12.0s	5	Core-8325-01
INC-0110	2026-09-01T10:03:00	2026-09-01T10:03:10	10.0s	4	Access-6100-03
WORKFLO W-0111	2026-09-01T10:03:15	2026-09-01T10:03:15	0.0s	1	Core-8325-01
WORKFLO W-0112	2026-09-01T10:04:20	2026-09-01T10:04:20	0.0s	1	Core-8325-01
WORKFLO W-0113	2026-09-01T10:04:45	2026-09-01T10:04:45	0.0s	1	Access-6100-01
WORKFLO W-0114	2026-09-01T10:05:00	2026-09-01T10:05:00	0.0s	1	Access-6100-04
WORKFLO W-0115	2026-09-01T10:05:05	2026-09-01T10:05:05	0.0s	1	Access-6100-04

Severity Matrix

Severity Level	Event Count	% of Total
Critical	35	8.8%
Warning / Error	114	28.6%
Info	249	62.6%
Total	398	100%

Network Domain Classification

Domain Tier	Event Count	% of Total
Layer 0 - Hardware	3	0.8%
Layer 1 - Physical	90	22.6%
Layer 2 - Switching	66	16.6%
Layer 2 - VXLAN Overlay	1	0.3%
Layer 3 - Routing	17	4.3%
Layer 3 - VXLAN Underlay	43	10.8%
Layer 4 - Management	30	7.5%
Layer 4 - Security	21	5.3%
Unknown / Other	127	31.9%

Detailed Investigation Report

Network Incident Investigation Report

Generated: 2026-06-29T15:07:36Z

Executive Summary

- Total incidents reconstructed: 48
- Total events analyzed: 398
- Total causal links inferred: 322
- Affected devices: 192.168.1.10, 192.168.1.104, Access-6100-02, Access-6100-03, Access-6100-04, Access-6100-05, Core-8325-01, Dist-6300-01, Edge-6300-01, router-1, router-2

Probable Initiating Triggers

- Incident INC-0007 -> Root Cause: dot1x_failure (device=192.168.1.104, score=54.3)
- Incident INC-0009 -> Root Cause: interface_down (device=192.168.1.10, score=178.6)
- Incident INC-0014 -> Root Cause: stp_topology_change (device=192.168.1.10, score=93.9)
- Incident INC-0017 -> Root Cause: power_failure (device=192.168.1.10, score=220.6)

- Incident INC-0028 -> Root Cause: crc_errors (device=192.168.1.10, score=192.8)
- Incident INC-0030 -> Root Cause: bgp (device=router-2, score=122.2)
- Incident INC-0036 -> Root Cause: transceiver (device=Dist-6300-01, score=188.6)
- Incident INC-0038 -> Root Cause: dot1x_failure (device=Access-6100-02, score=54.3)
- Incident INC-0039 -> Root Cause: power_failure (device=Core-8325-01, score=217.9)
- Incident INC-0044 -> Root Cause: crc_errors (device=192.168.1.10, score=189.2)
- Incident INC-0046 -> Root Cause: dot1x_failure (device=192.168.1.10, score=54.9)
- Incident INC-0051 -> Root Cause: transceiver (device=Dist-6300-01, score=197.8)
- Incident INC-0053 -> Root Cause: dot1x_failure (device=Access-6100-02, score=54.3)
- Incident INC-0054 -> Root Cause: power_failure (device=Core-8325-01, score=217.9)
- Incident INC-0060 -> Root Cause: interface_down (device=router-1, score=196.4)
- Incident INC-0071 -> Root Cause: crc_errors (device=192.168.1.10, score=189.5)
- Incident INC-0076 -> Root Cause: dot1x_failure (device=192.168.1.10, score=55.8)
- Incident INC-0081 -> Root Cause: transceiver (device=192.168.1.104, score=190.1)
- Incident INC-0083 -> Root Cause: transceiver (device=Edge-6300-01, score=189.5)
- Incident INC-0086 -> Root Cause: transceiver (device=Dist-6300-01, score=190.4)
- Incident INC-0087 -> Root Cause: dot1x_failure (device=Access-6100-04, score=54.3)
- Incident INC-0088 -> Root Cause: power_failure (device=Core-8325-01, score=217.9)
- Incident INC-0095 -> Root Cause: transceiver (device=Dist-6300-01, score=192.2)
- Incident INC-0096 -> Root Cause: dot1x_failure (device=Access-6100-03, score=54.3)
- Incident INC-0098 -> Root Cause: power_failure (device=Core-8325-01, score=218.2)
- Incident INC-0099 -> Root Cause: crc_errors (device=Access-6100-05, score=188.9)
- Incident INC-0104 -> Root Cause: transceiver (device=Dist-6300-01, score=192.8)
- Incident INC-0108 -> Root Cause: dot1x_failure (device=Access-6100-02, score=54.3)
- Incident INC-0109 -> Root Cause: power_failure (device=Core-8325-01, score=218.2)
- Incident INC-0110 -> Root Cause: crc_errors (device=Access-6100-03, score=188.9)

Incident Overview

- INC-0007: events=2, duration=0.0s, primary_issue=dot1x_failure
- INC-0008: events=5, duration=64.0s, primary_issue=ssh_bruteforce
- INC-0009: events=5, duration=145.0s, primary_issue=interface_down
- INC-0014: events=5, duration=471.0s, primary_issue=stp_topology_change
- INC-0017: events=13, duration=195.0s, primary_issue=power_failure
- INC-0028: events=17, duration=360.0s, primary_issue=crc_errors

- INC-0030: events=7, duration=471.0s, primary_issue=bgp
- INC-0033: events=3, duration=40.0s, primary_issue=ssh_bruteforce
- INC-0036: events=4, duration=3.0s, primary_issue=transceiver
- INC-0038: events=2, duration=3.0s, primary_issue=dot1x_failure
- INC-0039: events=4, duration=9.0s, primary_issue=power_failure
- INC-0044: events=5, duration=73.0s, primary_issue=crc_errors
- INC-0046: events=4, duration=28.0s, primary_issue=dot1x_failure
- INC-0051: events=7, duration=241.0s, primary_issue=transceiver
- INC-0052: events=4, duration=15.0s, primary_issue=ssh_bruteforce
- INC-0053: events=2, duration=8.0s, primary_issue=dot1x_failure
- INC-0054: events=4, duration=25.0s, primary_issue=power_failure
- INC-0060: events=12, duration=305.0s, primary_issue=interface_down
- INC-0071: events=6, duration=120.0s, primary_issue=crc_errors
- INC-0076: events=7, duration=48.0s, primary_issue=dot1x_failure
- INC-0079: events=3, duration=40.0s, primary_issue=ssh_bruteforce
- INC-0081: events=9, duration=9.0s, primary_issue=transceiver
- INC-0083: events=7, duration=0.024s, primary_issue=transceiver
- INC-0086: events=10, duration=8.614s, primary_issue=transceiver
- INC-0087: events=2, duration=5.983s, primary_issue=dot1x_failure
- INC-0088: events=4, duration=14.433s, primary_issue=power_failure
- INC-0089: events=2, duration=5.995s, primary_issue=ssh_bruteforce
- INC-0095: events=16, duration=179.892s, primary_issue=transceiver
- INC-0096: events=2, duration=4.102s, primary_issue=dot1x_failure
- INC-0097: events=2, duration=5.14s, primary_issue=ssh_bruteforce
- INC-0098: events=5, duration=12.214s, primary_issue=power_failure
- INC-0099: events=4, duration=12.656s, primary_issue=crc_errors
- INC-0104: events=20, duration=241.0s, primary_issue=transceiver
- INC-0107: events=2, duration=4.0s, primary_issue=ssh_bruteforce
- INC-0108: events=2, duration=6.0s, primary_issue=dot1x_failure
- INC-0109: events=5, duration=12.0s, primary_issue=power_failure
- INC-0110: events=4, duration=10.0s, primary_issue=crc_errors
- INC-0013: events=1, duration=0.0s, primary_issue=admin_auth_failure
- INC-0015: events=1, duration=0.0s, primary_issue=ssh_bruteforce

- INC-0025: events=1, duration=0.0s, primary_issue=standalone_alert
- INC-0031: events=7, duration=320.0s, primary_issue=stp_topology_change
- INC-0034: events=1, duration=0.0s, primary_issue=temperature
- INC-0045: events=1, duration=0.0s, primary_issue=standalone_alert
- INC-0059: events=5, duration=446.0s, primary_issue=stp_topology_change
- INC-0062: events=1, duration=0.0s, primary_issue=fan_failure
- INC-0063: events=1, duration=0.0s, primary_issue=bgp_session_lost
- INC-0064: events=1, duration=0.0s, primary_issue=admin_auth_failure
- INC-0072: events=1, duration=0.0s, primary_issue=standalone_alert

Detailed Incident Chains

INC-0007

Failure Sequence:

- dot1x_failure ×2 (error)
- dot1x_failure (error)

Status: Active

Duration: 0.0s

INC-0008

Failure Sequence:

- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (critical)

Status: Active

Duration: 64.0s

INC-0009

Failure Sequence:

- interface_down ×2 (info)
- interface_down (info)

- crc_errors ×2 (warning)
- crc_errors (warning)

Recovery Sequence:

- transceiver ×2 (info)

Status: Recovering

Duration: 145.0s

INC-0014

Failure Sequence:

- stp_topology_change (info)
- stp_topology_change ×2 (info)
- stp_topology_change ×2 (warning)
- ospf_neighbor_down ×2 (warning)

Recovery Sequence:

- bgp_session_established ×2 (info)

Status: Recovering

Duration: 471.0s

INC-0017

Failure Sequence:

- power_failure (critical)
- power_failure ×2 (critical)
- interface_down (critical)
- interface_down (critical)
- stp_topology_change (warning)
- interface_down (error)
- interface_down (info)
- bgp (info)
- fan_failure (warning)
- fan_failure ×2 (warning)
- ospf_neighbor_down (info)

- dot1x_failure (error)
- ospf_neighbor_down (info)

Status: Active

Duration: 195.0s

INC-0028

Failure Sequence:

- crc_errors (warning)
- crc_errors (warning)
- interface_down (critical)
- stp_topology_change (warning)
- interface_down (critical)
- stp_topology_change (warning)
- bgp (warning)
- ospf_neighbor_down (warning)
- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- radius_recovered (critical)
- dot1x_failure (error)

Recovery Sequence:

- bgp (warning)
- ospf (warning)

Status: Recovering

Duration: 360.0s

INC-0030

Failure Sequence:

- fan_failure (warning)
- bgp_session_lost (critical)

- bgp (warning)
- power (info)
- stp_topology_change (info)
- radius_recovered (info)
- radius_recovered (info)

Status: Active

Duration: 471.0s

INC-0033

Failure Sequence:

- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (critical)

Status: Active

Duration: 40.0s

INC-0036

Failure Sequence:

- transceiver (info)
- interface_down (info)
- ospf_neighbor_down (warning)
- bgp_session_lost (warning)

Status: Active

Duration: 3.0s

INC-0038

Failure Sequence:

- dot1x_failure ×2 (error)
- port_blocked (warning)

Status: Active

Duration: 3.0s

INC-0039

Failure Sequence:

- power_failure (critical)
- fan_failure (warning)
- thermal (warning)
- linecard_disabled (critical)

Status: Active

Duration: 9.0s

INC-0044

Failure Sequence:

- crc_errors (warning)
- interface_down (critical)
- stp_topology_change (warning)
- interface_down (critical)
- stp_topology_change (warning)

Status: Active

Duration: 73.0s

INC-0046

Failure Sequence:

- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- radius_recovered (critical)

Status: Active

Duration: 28.0s

INC-0051

Failure Sequence:

- transceiver (warning)

- interface_down (info)
- interface_down (info)
- ospf_neighbor_down (warning)

Recovery Sequence:

- transceiver (info)
- interface_up (info)
- ospf_neighbor_up (info)

Status: Resolved

Duration: 241.0s

INC-0052

Failure Sequence:

- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (critical)

Status: Active

Duration: 15.0s

INC-0053

Failure Sequence:

- dot1x_failure ×2 (error)
- raw (warning)

Status: Active

Duration: 8.0s

INC-0054

Failure Sequence:

- power_failure (critical)
- fan_failure (warning)
- thermal (warning)

- thermal (critical)

Status: Active

Duration: 25.0s

INC-0060

Failure Sequence:

- crc_errors (warning)
- crc_errors (warning)
- interface_down (critical)
- interface_down (error)
- interface_down (info)
- stp_topology_change (warning)
- interface_down (critical)
- ospf_neighbor_down (info)
- stp_topology_change (warning)
- bgp (warning)
- ospf_neighbor_down (warning)
- ssh_bruteforce (info)

Status: Active

Duration: 305.0s

INC-0071

Failure Sequence:

- crc_errors (warning)
- interface_down (critical)
- stp_topology_change (warning)
- interface_down (critical)
- stp_topology_change (warning)
- ospf_neighbor_down (warning)

Status: Active

Duration: 120.0s

INC-0076

Failure Sequence:

- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- dot1x_failure (error)
- radius_recovered (critical)
- dot1x_failure (error)

Status: Active

Duration: 48.0s

INC-0079

Failure Sequence:

- ssh_bruteforce (warning)
- ssh_bruteforce (warning)
- ssh_bruteforce (critical)

Status: Active

Duration: 40.0s

INC-0081

Failure Sequence:

- transceiver (info)
- interface_down (info)
- interface_down (info)
- ospf_interface_down (info)
- ospf_neighbor_down (warning)
- route_recalculation_started (info)
- route_recalculation_completed (info)
- bgp_session_lost (warning)
- route_withdrawal (info)

Status: Active

Duration: 9.0s

INC-0083

Failure Sequence:

- transceiver (info)
- interface_down (info)
- interface_down (info)
- ospf_interface_down (info)
- ospf_neighbor_down (warning)
- ospf (info)
- ospf (info)

Status: Active

Duration: 0.024s

INC-0086

Failure Sequence:

- transceiver (info)
- interface_down (info)
- interface_down (info)
- ospf_interface_down (info)
- ospf_neighbor_down (warning)
- ospf (info)
- ospf (info)
- bgp_session_lost (warning)
- route_withdrawal (info)
- route_withdrawal (info)

Status: Active

Duration: 8.614s

INC-0087

Failure Sequence:

- dot1x_failure ×3 (error)

- port_blocked (warning)

Status: Active

Duration: 5.983s

INC-0088

Failure Sequence:

- power_failure (critical)
- fan_failure (warning)
- thermal (warning)
- thermal (warning)

Status: Active

Duration: 14.433s

INC-0089

Failure Sequence:

- ssh_bruteforce ×3 (warning)
- ssh_source_blocked (critical)

Status: Active

Duration: 5.995s

INC-0095

Failure Sequence:

- transceiver (info)
- interface_down (info)
- interface_down (info)
- ospf_neighbor_down (warning)
- bgp_session_lost (warning)
- ospf (info)
- ospf (info)
- bgp_session_lost (warning)
- route_recalculation_started (info)
- route_recalculation_completed (info)

Recovery Sequence:

- transceiver (info)
- interface_up (info)
- interface_up (info)
- ospf_neighbor_up (info)
- bgp_session_established (info)
- routes_relearned (info)

Status: Resolved

Duration: 179.892s

INC-0096

Failure Sequence:

- dot1x_failure ×3 (error)
- port_blocked (warning)

Status: Active

Duration: 4.102s

INC-0097

Failure Sequence:

- ssh_bruteforce ×3 (warning)
- ssh_source_blocked (critical)

Status: Active

Duration: 5.14s

INC-0098

Failure Sequence:

- power_failure (critical)
- fan_failure (warning)
- thermal (warning)
- thermal (warning)
- linecard_disabled (critical)

Status: Active

Duration: 12.214s

INC-0099

Failure Sequence:

- crc_errors ×2 (warning)
- interface_down (info)
- interface_down (info)
- lldp (info)

Status: Active

Duration: 12.656s

INC-0104

Failure Sequence:

- route_withdrawal (info)
- routes_withdrawn (info)
- transceiver ×2 (info)
- interface_down ×2 (info)
- interface_down ×2 (info)
- ospf_interface_down ×2 (info)
- ospf_neighbor_down ×2 (warning)
- route_recalculation_started ×2 (info)
- route_recalculation_completed ×2 (info)
- bgp_session_lost ×2 (warning)
- route_withdrawal (info)
- bgp_session_lost (warning)
- lldp (info)

Recovery Sequence:

- transceiver (info)
- interface_up (info)
- interface_up (info)
- ospf_interface_up (info)

- ospf_neighbor_up (info)
- bgp_session_established (info)
- routes_relearned (info)

Status: Resolved

Duration: 241.0s

INC-0107

Failure Sequence:

- ssh_bruteforce ×3 (warning)
- ssh_source_blocked (critical)

Status: Active

Duration: 4.0s

INC-0108

Failure Sequence:

- dot1x_failure ×3 (error)
- port_blocked (warning)

Status: Active

Duration: 6.0s

INC-0109

Failure Sequence:

- power_failure (critical)
- fan_failure (warning)
- thermal (warning)
- thermal (warning)
- linecard_disabled (critical)

Status: Active

Duration: 12.0s

INC-0110

Failure Sequence:

- crc_errors ×2 (warning)
- interface_down (info)
- interface_down (info)
- lldp (info)

Status: Active

Duration: 10.0s

INC-0013

Failure Sequence:

- admin_auth_failure ×2 (warning)

Status: Active

Duration: 0.0s

INC-0015

Failure Sequence:

- ssh_bruteforce ×2 (critical)

Status: Active

Duration: 0.0s

INC-0025

Failure Sequence:

- raw (warning)

Status: Active

Duration: 0.0s

INC-0031

Failure Sequence:

- stp_topology_change (info)

Recovery Sequence:

- interface_up (info)
- interface_up (info)
- bgp_session_established (info)
- bgp (warning)
- ospf_neighbor_up (info)
- ospf (info)

Status: Active

Duration: 320.0s

INC-0034

Failure Sequence:

- temperature (warning)

Status: Active

Duration: 0.0s

INC-0045

Failure Sequence:

- raw (warning)

Status: Active

Duration: 0.0s

INC-0059

Failure Sequence:

- raw (warning)
- stp_topology_change (info)
- stp_topology_change (info)
- config_change (info)

Recovery Sequence:

- bgp (info)

Status: Active

Duration: 446.0s

INC-0062

Failure Sequence:

- fan_failure (warning)

Status: Active

Duration: 0.0s

INC-0063

Failure Sequence:

- bgp_session_lost (critical)

Status: Active

Duration: 0.0s

INC-0064

Failure Sequence:

- admin_auth_failure (error)

Status: Active

Duration: 0.0s

INC-0072

Failure Sequence:

- raw (critical)

Status: Active

Duration: 0.0s

Operational Workflows Detected

Workflow: WORKFLOW-0001

- **Status:** Successful
- **Incident Detected:** No

• Sequence Summary:

- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- tunnel_nexthop_delete (info)
- tunnel_activating (info)
- vxlan_interface (info)
- vni_delete (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)
- tunnel_operational (info)
- tunnel_nexthop_delete (info)

- tunnel_operational (info) x9

Workflow: WORKFLOW-0003

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- config_change (info)

Workflow: WORKFLOW-0011

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- mac_auth (info)

Workflow: WORKFLOW-0016

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- bgp_session_established (info)
- bgp (info)
- config_change (info)

Workflow: WORKFLOW-0019

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- interface_up (info) x2
- stp_topology_change (info)
- bgp (info)

Workflow: WORKFLOW-0022

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**

- lldp (info) x4

Workflow: WORKFLOW-0026

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - stp_topology_change (info) x2

Workflow: WORKFLOW-0027

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - authentication (info)
 - config_change (info)

Workflow: WORKFLOW-0029

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - interface_down (info)

Workflow: WORKFLOW-0035

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - authentication (info)

Workflow: WORKFLOW-0041

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - config_change (info)

Workflow: WORKFLOW-0049

- **Status:** Successful

- **Incident Detected:** No
- **Sequence Summary:**
- power (info)

Workflow: WORKFLOW-0058

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- config_change (info)

Workflow: WORKFLOW-0061

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- interface_down (info)

Workflow: WORKFLOW-0068

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- stp_topology_change (info)
- bgp_session_established (info)
- ospf_neighbor_down (info)
- ospf_neighbor_up (info)

Workflow: WORKFLOW-0069

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- config_change (info)

Workflow: WORKFLOW-0075

- **Status:** Successful
- **Incident Detected:** No

- **Sequence Summary:**
- stp_topology_change (info)
- ospf_neighbor_up (info)

Workflow: WORKFLOW-0080

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- power (info)

Workflow: WORKFLOW-0082

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- interface_down (info) x2
- ospf_neighbor_down (info)
- ospf_interface_down (info) x2
- tunnel_nexthop_delete (info)
- interface_down (info)
- tunnel_nexthop_delete (info)
- vtep_deleted (info)
- tunnel_activating (info) x2
- vni_delete (info) x2

Workflow: WORKFLOW-0084

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- raw (info)
- lldp (info)

Workflow: WORKFLOW-0090

- **Status:** Successful
- **Incident Detected:** No

- **Sequence Summary:**

- transceiver (info)
- interface_up (info) x2
- ospf_interface_up (info)
- ospf_neighbor_up (info)
- bgp_session_established (info)
- routes_relearned (info)

Workflow: WORKFLOW-0092

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- config_change (info)

Workflow: WORKFLOW-0094

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- config_change (info)

Workflow: WORKFLOW-0100

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- raw (info)

Workflow: WORKFLOW-0101

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
- raw (info) x2

Workflow: WORKFLOW-0103

- **Status:** Successful

- **Incident Detected:** No
- **Sequence Summary:**
 - ntp (info)
 - snmp (info)
 - ntp (info)
 - snmp (info)

Workflow: WORKFLOW-0105

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - config_change (info)
 - raw (info) x2

Workflow: WORKFLOW-0106

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - mac_auth (info) x2

Workflow: WORKFLOW-0112

- **Status:** Successful
- **Incident Detected:** No
- **Sequence Summary:**
 - raw (info)

Standalone Alerts

The following high-severity events were detected but do not appear to be part of a larger cascading incident:

- 192.168.1.104: admin_auth_failure (warning) - Authentication failure for user admin from 192.168.1.99
- 192.168.1.104: ssh_bruteforce (critical) - SSH login failed from IP 203.0.113.5: Maximum attempts exceeded
- 192.168.1.10: raw (warning) - 802.1x: Authentication retry for client 11:22:33:44:55:66 on port 1/1/15
- 192.168.1.10: interface_up (info) - Port 1/1/7 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/8 is now on-line
- 192.168.1.10: stp_topology_change (info) - Instance 0: Topology converged, no changes

- 192.168.1.10: bgp_session_established (info) - BGP peer 10.0.0.6 session established
- router-2: bgp (warning) - rpd[1190]: [daemon.info] BGP_NEIGHBOR_STATE_CHANGED: bgp peer 192.168.1.10 state changed from Idle to Established
- 192.168.1.10: ospf_neighbor_up (info) - OSPF neighbor 192.168.3.1 on VLAN 30 changed state from DOWN to FULL
- router-2: ospf (info) - rpd[1190]: [daemon.info] RPD_OSPF_NBRUP: OSPF neighbor 192.168.3.1 on ge-0/0/2.0 state changed from Down to Full
- router-2: temperature (warning) - chassisd[330]: [hw.warn] Temperature sensor 1 reading elevated: 52C (threshold 65C)
- 192.168.1.10: raw (warning) - 802.1x: Authentication retry for client 11:22:33:44:55:66 on port 1/1/15
- 192.168.1.10: raw (warning) - 802.1x: Authentication retry for client 11:22:33:44:55:66 on port 1/1/15
- 192.168.1.10: stp_topology_change (info) - Instance 0: Topology change detected on port 1/1/30, recalculating spanning tree
- 192.168.1.10: stp_topology_change (info) - Instance 0: Topology converged
- router-1: bgp (info) - %BGP-5-ADJCHANGE: neighbor 192.168.1.10 Up
- 192.168.1.10: config_change (info) - Configuration saved by admin via SSH from 192.168.1.200
- 192.168.1.10: fan_failure (warning) - Fan tray 2 speed nominal
- 192.168.1.10: bgp_session_lost (critical) - BGP peer 10.0.0.6 session Down, hold timer expired
- router-1: admin_auth_failure (error) - %SNMP-3-AUTHFAIL: Authentication failure for SNMP req from host 10.0.0.250
- router-1: raw (critical) - %ENVIRONMENT-1-ALERT: Temp: Inlet 1 Temperature reading 41C, threshold 65C - normal

Routine & Unlinked Noise

The following events were classified as non-actionable noise or routine informational activity:

- 192.168.1.10: ntp (info) - Synchronized to NTP server 10.0.0.1, offset 0.012ms
- 192.168.1.104: snmp (info) - Connection with 192.168.1.50 closed
- 192.168.1.10: snmp (info) - Connection with 192.168.1.50 closed
- 192.168.1.10: interface_up (info) - Port 1/1/9 is now on-line
- 192.168.1.104: interface_up (info) - Port 1/1/1 is now on-line
- 192.168.1.10: lldp (info) - LLDP neighbor discovered on port 1/1/1: remote device router-1 (10.0.0.2)
- 192.168.1.10: lldp (info) - LLDP neighbor discovered on port 1/1/3: remote device switch-2 (10.0.0.4)
- router-1: lldp (info) - %LLDP-5-NEIGHBOR: LLDP neighbor up: switch-1 (192.168.1.10) on GigabitEthernet0/1
- 192.168.1.104: vlan (info) - Vlan 10 is created
- 192.168.1.104: lldp (info) - LLDP neighbor 00:25:B3:11:22:33 discovered on port 1/1/10

- 192.168.1.104: dot1x_logout (info) - 802.1x: Client 00:11:22:33:44:55 logged out from port 1/1/5
- 192.168.1.104: ntp (info) - NTP synchronized to time server 132.163.97.5
- router-1: interface_up (error) - %LINK-3-UPDOWN: Interface GigabitEthernet0/1, changed state to up
- router-1: interface_up (info) - %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0/1, changed state to up
- 192.168.1.10: ntp (info) - Synchronized to NTP server 10.0.0.1, offset 0.008ms
- 192.168.1.10: interface_up (info) - Port 1/1/20 is now on-line
- 192.168.1.10: snmp (info) - Connection with 192.168.1.50 closed
- 192.168.1.10: interface_up (info) - Port 1/1/20 is now on-line
- Core-8325-01: ntp (info) - NTP synchronized with server 192.168.1.1
- Core-8325-01: snmp (info) - Connection with 192.168.1.50 closed
- Access-6100-03: lldp (info) - LLDP neighbor discovered on port 1/1/5
- 192.168.1.10: ntp (info) - Synchronized to NTP server 10.0.0.1, offset 0.005ms
- 192.168.1.10: interface_up (info) - Port 1/1/20 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/7 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/9 is now on-line
- Core-8325-01: ntp (info) - Synchronized to NTP server 10.0.0.1
- Core-8325-01: snmp (info) - Connection with 192.168.1.50 closed
- 192.168.1.10: ntp (info) - Synchronized to NTP server 10.0.0.1, offset 0.006ms
- 192.168.1.10: lldp (info) - LLDP neighbor discovered on port 1/1/1: remote device router-1 (10.0.0.2)
- router-1: lldp (info) - %LLDP-5-NEIGHBOR: LLDP neighbor up: core-switch (192.168.1.10) on GigabitEthernet0/1
- 192.168.1.10: lldp (info) - LLDP neighbor discovered on port 1/1/2: remote device router-2 (10.0.0.6)
- 192.168.1.10: lldp (info) - LLDP neighbor discovered on port 1/1/4: remote device switch-3 (10.0.0.9)
- 192.168.1.10: interface_up (info) - Port 1/1/20 is now on-line
- 192.168.1.10: snmp (info) - Connection with 192.168.1.50 closed
- 192.168.1.10: interface_up (info) - Port 1/1/7 is now on-line
- router-1: interface_up (error) - %LINK-3-UPDOWN: Interface GigabitEthernet0/2, changed state to up
- router-1: interface_up (info) - %LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet0/2, changed state to up
- 192.168.1.10: interface_up (info) - Port 1/1/8 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/20 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/55 is now on-line
- 192.168.1.10: interface_up (info) - Port 1/1/56 is now on-line

- 192.168.1.10: radius_recovered (info) - 802.1x: Authentication succeeded for client AA:11:BB:22:CC:33 on port 1/1/40 (backup RADIUS)
- 192.168.1.10: radius_recovered (info) - 802.1x: Authentication succeeded for client BB:22:CC:33:DD:44 on port 1/1/41 (backup RADIUS)
- Core-8325-01: vlan (info) - VLAN 100 created
- Core-8325-01: ntp (info) - NTP synchronized with time source 192.168.1.1
- Core-8325-01: ntp (info) - NTP synchronized with server 192.168.10.1
- Core-8325-01: ntp (info) - NTP synchronized with server 192.168.10.1
- Core-8325-01: vlan (info) - VLAN 200 created
- Access-6100-01: lldp (info) - LLDP neighbor discovered on port 1/1/12
- Access-6100-04: interface_up (info) - Port 1/1/20 is now on-line
- Access-6100-04: interface_up (info) - Port 1/1/21 is now on-line

Confidence and Limitations

- Causality is inferred from temporal and contextual heuristics, not strict proof.
- Confidence increases when links have strong timing, device/interface alignment, and severity progression.

Recommendations

- Prioritize remediation on root-linked interfaces/devices before downstream symptoms.
- Add monitoring alerts for repeated trigger subtypes and interface recurrence.
- Validate inferred root causes with device-level diagnostics and config audit.