
Command probe | Measured joint / EEF response unavailable
Actual transform function: input x=0.5
Normalized command
0.50
0.45
0.40
0.35
0.30
0.25
0.20
0.15
0.3
0.4
0.5
0.6
0.7
0.8
0.9
1.0
Arm command gain
Reference target calculation; NOT measured EEF
Target delta (mm)
50
45
40
35
30
25
20
15
0.3
0.4
0.5
0.6
0.7
0.8
0.9
1.0
Arm command gain