



Republic of the Philippines
Department of Agriculture
BUREAU OF FISHERIES AND AQUATIC RESOURCES
REGIONAL FISHERIES LABORATORY XII
J. Catolico St., Lagao, General Santos City

Document Type Work Instruction	Revision No: 0	Date Adopted: 13 Aug 2019	Page No: Page 1 of 3
Document Code: WI-01-01	METHOD VERIFICATION		

Introduction

This work instruction provides procedure in method verification to meet specific requirements according to sub clause 7.2.2 of PNS ISO/IEC 17025:2017. This procedure applies to all parameters analyzed in the RFL XII.

This procedure covers the following:

- Working Range Determination and Validation of Calibration Curve.
- Method Detection Level
- Determination of accuracy and precision of the method.
- Preparation and Application of Quality Control Chart.
- Estimation of Measurement Uncertainty.
- Determination of Limit of Detection (LOD) and Limit of Quantification (LOQ).

1. Responsibility

1. Quality Assurance Manager
2. Technical Manager
3. Laboratory Analyst

2. Procedure

2.1. Include the following required method verification plan in each parameter analyzed.

1. Working Range Verification.
2. Method Detection Level (LOD and LOQ).
3. Verification of the accuracy and precision of the method.
4. Preparation and Application of Quality Control Chart.
5. Target concentration of the analyte.

Prepared by: MA. MAURICE A. BANQUILING Quality Assurance Manager	Reviewed and Approved by: EUGENE GAY B. JAMORA Laboratory Manager
--	---



Republic of the Philippines
Department of Agriculture
BUREAU OF FISHERIES AND AQUATIC RESOURCES
REGIONAL FISHERIES LABORATORY XII
J. Catolico St., Lagao, General Santos City

Document Type Work Instruction	Revision No: 0	Date Adopted: 13 Aug 2019	Page No: Page 2 of 3
Document Code: WI-01-01	METHOD VERIFICATION		

2.2. Perform Analysis per parameter as specified in the applicable WI-01.

2.3. Data Reduction/Evaluation

1. Record all the results in the logbook of the parameters being analyzed.
2. Compute concentration of parameter being analyzed.
3. Calculate the following from the raw data;
 - a. % Recovery
 - b. Repeatability
 - c. Method Detection Level (LOD and LOQ).
 - d. Reproducibility

2.4. Interpret all the data generated.

1. Submit the records to the laboratory manager for final approval.

3. Documentation

3.1. Data and working sheet generated by these procedures shall be maintained by following SOP-11 and SOP-14.

3.2. Standard Methods for the Examination of Water and Wastewater, 20th ed.

APHA (American Public Health Association)

AWWA (American Water Works Association)

WEF (Water Environment Federation)

3.3. PNS ISO/IEC 17025:2017.

Prepared by: MA. MAURICE A. BANQUILING Quality Assurance Manager	Reviewed and Approved by: EUGENE GAY B. JAMORA Laboratory Manager
--	---



Republic of the Philippines
Department of Agriculture
BUREAU OF FISHERIES AND AQUATIC RESOURCES
REGIONAL FISHERIES LABORATORY XII
J. Catolico St., Lagao, General Santos City

Document Type Work Instruction	Revision No: 0	Date Adopted: 13 Aug 2019	Page No: Page 3 of 3
Document Code: WI-01-01	METHOD VERIFICATION		

4. Document History

Revision No.	Issue Date	Original Entry	Revised as	Recall Date

Prepared by: MA. MAURICE A. BANQUILING Quality Assurance Manager	Reviewed and Approved by: EUGENE GAY B. JAMORA Laboratory Manager
---	--