

CE RoHS

- Thank you for purchasing and using this product. Before using the product, please read the manual carefully and use the product correctly, in order to avoid damage to the equipment, such as all consequences caused by abnormal operation. The company will not take any responsibility.
- ★ The pictures in this manual are used to guide the user's operation and are for reference only. Please refer to the actual product for details.

Figure 1 illustrates the components of the proposed system. It includes a 'Main body' which features a 'Status Indicator' and a 'Reset Button'. A 'Waterproof Probe' is also shown as a separate component.



Temperature sensor

3/8-inch

Alloy Probe X2

Fully submerge the probe in water during testing, wait 20 seconds until temperature stabilizes for accurate readings. Do not let the probe touch container bottom or inner walls, otherwise measurement error will occur.

Install the product on the wall with double-sided tape or place it in the space you want to measure.



Diagram of a door with a handle and a lock mechanism.

Do not install the product outdoors, on an unstable base, or anywhere unprotected from the rain. The installation place of the door sensor should be smooth, flat, dry and clean.

Open the battery cover

Quick connection mode:
Press and hold the button for 5 seconds, the indicator light will flash slowly, and follow the prompts to add from the gateway app. When unable to connect to the network, please use compatibility mode.

Compatibility mode:
Press and hold the button for 10 seconds, the indicator light will flash quickly, and follow the prompts to add from the gateway app.

***The Zigbee version product must be connected to the Zigbee gateway to function properly and upload data to the server/APP**

After setting parameters on the APP, the device needs to be triggered once to synchronize the parameters.
For example, Press the button once

Product Name	Multi-Parameter Water Quality Monitor
Wireless Protocol	Zigbee
Working Voltage	DC3V
Battery Type	LR03-1.5V/AAA*2
Standby Current	≤20uA
Probe Measure Range	0 ℃ ~60 ℃
Operating Temperature	10 ℃ ~60 ℃
Operating Humidity	0% ~ 99% RH

ZG-101TDS	
EC	0-20000 µS/cm, ±1%FS
TDS	0-999 ppm ±1%FS
Salinity	0.0-2.0 ‰, ±1%FS
ZG-109TDS	
EC	0-20000 µS/cm, ±2%FS
TDS	0-13000 ppm ±2%FS
Salinity	0.0-50.0 ‰, ±2%FS
SG	1.000-1.050, ±0.001