FSM:

IDLE → ELAB: When flag_in = 1, indicating that there has been at least one bit flip.

ELAB > OUT: When done_bfd = 1, signaling the bfdensity_divider_serial has completed.



