




Parameter scaling factors for Material intensity RE (mat), Cost intensity RE (cost), Energy intensity Recycling (rec)

— mat=1, cost=1, rec=1	... mat=5, cost=1, rec=1	... mat=1, cost=1, rec=0.2
... mat=0, cost=0, rec=0	... mat=1, cost=5, rec=1	... mat=2, cost=5, rec=0.2
... mat=0.2, cost=0.2, rec=0.2	... mat=1, cost=1, rec=5	... mat=0.2, cost=2, rec=5
... mat=2, cost=2, rec=2	... mat=0.2, cost=1, rec=1	... mat=5, cost=0.2, rec=2
... mat=5, cost=5, rec=5	... mat=1, cost=0.2, rec=1	