Outside
$$T_{H} = 100^{\circ}\text{F}$$

$$Q_{H} = +6000 \text{ J}$$

$$W = 1500 \text{ J}$$

$$Q_{C} = -4500 \text{ J}$$
Inside
$$T_{C} = 85^{\circ}\text{F}$$