

Dashed line means switches move together. Two horizontal lines indicate iron core.