

Functional Specification Document

A unified blueprint translating business strategy into governed, measurable performance metrics.

Document Version	1.0
Generated Date	June 19, 2026
Industry Sector	Manufacturing
Organizational Level	Board
Scope of Performance Metrics	1 Approved Performance Metrics
Approval Status	DRAFT

Table of Contents


Document Control & Metadata	1
1. Executive Summary	2
2. KPI Landscape Overview	2
3. Strategic Traceability Matrix	3
4. Individual KPI Specifications	4
4.1 Overall Equipment Effectiveness (OEE)	4
5. Governance Framework	5
6. Reporting & Dashboard Requirements	6
7. Assumptions & Constraints	7
8. Implementation Considerations	8
9. Appendix	9

1. Executive Summary

This Functional Specification Document (FSD) establishes a unified, consulting-grade framework for Key Performance Indicators (KPIs) critical to the organization's strategic objectives. Aligned with the Board-level priorities of improving cash flow, enhancing gross margin, increasing process automation, and reducing defect rates, this document serves as the single source of truth for all stakeholders, including business leaders, steering committees, BI teams, data engineers, and ERP specialists. The initiative directly addresses significant business challenges such as customer churn and complaints, demand volatility, frequent machine downtime, high inventory levels impacting working capital, and the need for improved forecast accuracy. By providing clear, actionable definitions, calculation methodologies, and governance structures for each KPI, this FSD aims to foster a data-driven culture, enhance decision-making capabilities, and drive measurable improvements in operational excellence and financial performance. The framework emphasizes traceability from strategic objectives through to specific KPIs, ensuring that every metric contributes directly to achieving desired business outcomes. Key to this transformation is establishing robust data governance, ensuring data quality, and implementing clear ownership and accountability for both business performance and data integrity. The document details specific requirements for KPI calculation, data validation, exception handling, and reporting, ensuring that the resulting insights are reliable, timely, and actionable. Ultimately, this FSD is designed to empower the organization to navigate market complexities, optimize resource utilization, mitigate risks, and achieve sustainable competitive advantage through enhanced performance management.

2. KPI Landscape Overview

The following visual mind-map displays the KPI Landscape as a branching tree structure, routing from the core KPI Library through strategic categories down to individual approved metrics.



The following table provides a high-level catalog of all approved performance indicators within the scope of this transformation initiative.

KPI ID	KPI Name	Category	Functional Area
KPI-001	Overall Equipment Effectiveness (OEE)	Operational	Production

3. Strategic Traceability Matrix

This matrix illustrates the strategic alignment from executive objectives down to specific key performance indicators, providing visibility into strategic translation.

Strategic Objective	Business Challenge	KRA	Functional Area	KPI Name
Enhance Process Automation & Reduce Defect Rates → Demand Volatility → Operational Excellence → Production → Overall Equipment Effectiveness (OEE)	Frequent machine downtime in the assembly line affecting production output.	Operational Excellence	Production	Overall Equipment Effectiveness (OEE)

4. Individual KPI Specifications

Detailed functional blueprints for each approved metric, outlining definitions, lineage, calculations, and rules.

Metric 01: Overall Equipment Effectiveness (OEE)

KPI Category	Operational	Functional Area	Production
Business Owner	Operations Head	Data Owner	Production Manager

Business Definition

Overall Equipment Effectiveness (OEE) is a manufacturing metric that measures the percentage of planned production time that is truly productive. It integrates three key components: Availability Rate (time equipment is available to run), Performance Rate (how quickly equipment runs compared to its ideal speed), and Quality Rate (number of good parts produced versus total parts produced). The unit of measure is a percentage (%). Reporting frequency is Daily, with monthly aggregation for trend analysis. Measurement scope is per machine or production line.

Business Purpose & Strategic Relevance

This KPI is essential for measuring and improving the efficiency of manufacturing equipment, directly supporting the strategic objective to 'Enhance Process Automation' and 'Reduce Defect Rates'. It addresses the critical business challenge of 'frequent machine downtime in the assembly line affecting production output' by providing a holistic view of asset performance. OEE integrates Availability, Performance, and Quality, thereby pinpointing specific areas of waste and inefficiency. By monitoring OEE, the organization can make informed decisions regarding maintenance schedules, equipment upgrades, operator training, and process optimization. The business value derived includes reduced operational costs through minimized downtime, increased production throughput, improved product quality by identifying and rectifying issues that lead to defects, and ultimately, enhanced profitability. Without this KPI, the organization would lack a standardized, comprehensive measure to identify the root causes of production inefficiencies and track the effectiveness of improvement initiatives, potentially leading to continued high operational costs and missed production targets. The monthly review cadence, as noted in the metadata, is critical for tracking progress against improvement plans.

Calculation Methodology

Formula	Availability Rate * Performance Rate * Quality Rate
Numerator Details	Operating Time * Actual Throughput * Good Units
Denominator Details	Planned Production Time * Ideal Run Rate * Total Units
Calculation Logic	1. Calculate Availability Rate: (Planned Production Time - Downtime) / Planned Production Time. 2. Calculate Performance Rate: (Total Units / Operating Time) / Ideal Run Rate. 3. Calculate Quality Rate: Good Units / Total Units. 4. Multiply the three rates: Availability Rate * Performance Rate * Quality Rate to derive OEE.
Inclusion Rules	All production runs during planned operating hours. All units produced, including those that are scrapped or require rework. All downtime events, including planned and unplanned stops.
Exclusion Rules	Planned maintenance periods outside of scheduled production hours. Production runs for non-standard products or pilot batches not part of the regular production schedule. Downtime due to external factors not within the production team's control (e.g., power outages, raw material shortages - these should be tracked separately but may be excluded from OEE calculation depending on specific business rules).
Sample Worked Example	Assume a single production line operates for an 8-hour shift (480 minutes). Planned Production Time = 480 minutes. During the shift, there was 60 minutes of unplanned downtime (e.g., machine breakdown). Operating Time = 480 - 60 = 420 minutes. The line's Ideal Run Rate is 100 units per minute. Actual Throughput during operating time was 3500 units. Total Units Produced = 3500 units. Of these, 3360 units were good (passed quality inspection), and 140 were scrapped. 1. Availability Rate = (420 minutes / 480 minutes) = 0.875 (or 87.5%) 2. Performance Rate = (3500 units / 420 minutes) / 100 units/min = 8.33 units/min / 100 units/min = 0.0833 (This calculation seems incorrect based on the provided numbers. Let's re-evaluate based on standard OEE calculation. Performance Rate = Actual Output / Potential Output during Operating Time. Potential Output during Operating Time = Operating Time * Ideal Run Rate = 420 minutes * 100 units/min = 42,000 units. Performance Rate = 3500 units / 42,000 units = 0.0833. This still seems low. Let's assume the 'Actual Throughput' is the total units produced in the operating time, and the Ideal Run Rate is the maximum possible output in that time. If Ideal Run Rate is 100 units/min, then in 420 minutes, potential output is 42,000 units. If Actual Throughput is 3500 units, then Performance Rate = 3500 / 42000 = 0.0833. This implies a very slow run speed. Let's assume the 'Actual Throughput' is the number of units produced in the operating time, and the 'Ideal Run Rate' is the target speed. If the line *should* produce 100 units per minute, and it produced 3500 units in 420 minutes, its actual speed was 3500/420 = 8.33 units/min. So, Performance Rate = 8.33 / 100 = 0.0833. This is a very low performance rate. Let's adjust the example to be more realistic for illustration. Revised Sample Calculation: Assume a single production line operates for an 8-hour shift (480 minutes). Planned Production Time = 480 minutes. During the shift, there was 30 minutes of unplanned downtime (e.g., minor jam, setup adjustment). Operating Time = 480 - 30 = 450 minutes. The line's Ideal Run Rate is 50 units per minute. Actual Throughput during operating time was 20,000 units. Total Units Produced = 20,000 units. Of these, 19,000 units were good (passed quality inspection), and 1,000 were scrapped. 1. Availability Rate = (450 minutes / 480 minutes) = 0.9375 (or 93.75%) 2. Performance Rate = (20,000 units / 450 minutes) / 50 units/min = 44.44 units/min / 50 units/min = 0.8889 (or 88.89%) 3. Quality Rate = 19,000 good units / 20,000 total units = 0.95 (or 95%) 4. OEE = 0.9375 * 0.8889 * 0.95 = 0.7949 (or 79.49%)

Business Rules & Data Validation

Business Operating Rules	OEE is calculated based on standard production shifts. Downtime events must be logged with specific reasons. Ideal Run Rate is a pre-defined engineering standard. Good Units are defined by quality inspection criteria. The business calendar dictates planned production time.
Data Validation Rules	Availability Rate, Performance Rate, and Quality Rate must each be between 0% and 100%. Total Units must be greater than or equal to Good Units. Operating Time must be less than or equal to Planned Production Time. Ideal Run Rate must be a positive value. OEE must be between 0% and 100%.
Exception Handling Rules	If Planned Production Time is zero, OEE is undefined (or set to 0% with an alert). If Operating Time is zero, Availability Rate is 0%, and OEE is 0%. If Ideal Run Rate is zero, Performance Rate is undefined (or set to 0% with an alert). If Total Units is zero, Quality Rate is undefined (or set to 0% with an alert). If the denominator in any rate calculation is zero, that rate is considered zero.
Data Quality Expectations	Source data for downtime, production counts (total and good), and planned production schedules must be available by 08:00 UTC daily for the previous 24-hour period. Data completeness target is 99% for all required fields. Data accuracy target is 99.5% for production counts.

Recommended Source Systems

Recommended Source Systems: SAP Production Planning (PP) module for planned production orders and schedules. Shop floor data collection systems (e.g., MES) for real-time machine status, downtime events, actual throughput, and unit counts. Recommended ERP Finance Ledger for cost data related to downtime if applicable.

5. Governance Framework

To ensure metric consistency, accountability, and ongoing relevance, a formal governance framework is established for all approved KPIs. This structure assigns clear responsibilities and defines escalation paths.

Roles and Responsibilities

- **Business Owner:** Responsible for defining the business logic, validating calculation results, approving target thresholds, and driving operational performance based on metric insights.
- **Data Owner:** Accountable for technical lineage, data completeness, source-to-target mapping, ETL data quality checks, and resolving data ingestion or availability issues.
- **Escalation Path:** In case of data quality discrepancies or alignment disputes, issues are escalated to the Data Governance Committee and KPI Advisory Board for review and reconciliation.

Ownership and Governance Policy Matrix

Metric Name	Business Owner	Data Owner	Governance Policy Notes
Overall Equipment Effectiveness (OEE)	Operations Head	Production Manager	The Operations Head is the business owner responsible for setting OEE targets, reviewing monthly performance reports, and approving action plans for improvement. The Production Manager is the data owner responsible for ensuring the accuracy and completeness of shop floor data collection and its integration into reporting systems. Variances exceeding 10% from the previous period or target require immediate investigation and a documented explanation. A monthly KPI review meeting with the Operations leadership team will discuss OEE performance, identify root causes of deviations, and track progress on improvement initiatives. Sign-off on monthly OEE reports by the Operations Head is required.

6. Reporting & Dashboard Requirements

Visualization layout and threshold criteria dictate how data is displayed to support decision-making. The matrix below outlines reporting recommendations and performance thresholds for each metric.

Metric Name	Reporting Guidelines	Dashboard Placement	Threshold Guidance
Overall Equipment Effectiveness (OEE)	Visualization: Trend line chart showing daily OEE over time, with separate lines for Availability, Performance, and Quality rates. Drill-down dimensions: by production line, by shift, by product type, by downtime reason. Alerting rules: Trigger alerts if daily OEE drops below 75% (Red threshold) or if there's a significant deviation (>10%) from the previous day's OEE. Threshold levels: Green $\geq$ 85%, Amber 75%-85%, Red $<$ 75%.	Production Floor Control Dashboard, Operations Performance Dashboard, Executive Performance Dashboard (summary view).	Green ($\geq$ 85%): Indicates excellent operational efficiency, meeting or exceeding targets. Amber (75%-85%): Requires monitoring and targeted improvement actions to prevent further decline. Red ($<$ 75%): Indicates significant operational issues requiring immediate root cause analysis and corrective actions.

7. Assumptions & Constraints

A clear understanding of business and technical assumptions is critical for successful implementation. The following list represents consolidated baseline assumptions and constraints.

General Architectural Assumptions

- **Data Availability:** Source transactional tables are assumed to be loaded into the central reporting repository on a standard nightly batch cadence.
- **Fiscal Calendar:** Standard calendar year rules are assumed unless otherwise explicitly documented in specific financial indicators.
- **System Uptime:** Target source ERP ledgers are assumed to maintain 99.5% uptime during standard reporting extraction windows.

Metric-Specific Assumptions and Limitations

- **Overall Equipment Effectiveness (OEE):** Assumes that downtime events are accurately and consistently logged with clear reasons. Assumes the Ideal Run Rate is accurately defined and reflects optimal machine performance. Assumes that quality inspection criteria for 'Good Units' are consistently applied. Assumes that the SAP PP module and shop floor systems are integrated to provide timely data. Constraint: The accuracy of OEE is highly dependent on the discipline of shop floor data entry.

8. Implementation Considerations

Transitioning these specifications into functional BI tools requires rigorous testing, change management, and data reconciliation. Standard implementation considerations are outlined below.

Standard Implementation Guidelines

- **Data Reconciliation:** All KPI calculation outcomes must be audited and reconciled against official books of record or audited financial statements.
- **User Acceptance Testing (UAT):** Business owners must perform visual and numeric validation of dashboard mockups prior to production sign-off.
- **Change Management:** Training sessions and clear system documentation are required to support user onboarding and ensure high organizational adoption.

Metric-Specific Technical Considerations

- **Overall Equipment Effectiveness (OEE):** Implement robust data collection mechanisms on the shop floor, ensuring operators are trained and incentivized for accurate data entry. Establish a clear process for logging and categorizing downtime reasons. Define and validate the 'Ideal Run Rate' with engineering. Ensure seamless integration between shop floor systems and SAP PP. Conduct regular training sessions for the Production Manager and their team on OEE calculation, interpretation, and data validation. The Operations Head should champion the importance of OEE in daily production meetings to foster a culture of continuous improvement.

9. Appendix

KPI Glossary

- **KPI (Key Performance Indicator):** A quantifiable measure used to evaluate the success of an organization or activity in meeting performance objectives.
- **KRA (Key Result Area):** Primary focus areas of outcomes or outputs for which an organizational unit or role is responsible.
- **Numerator:** The upper portion of a division representing the measured subset of occurrences.
- **Denominator:** The lower portion of a division representing the total base population.

Data Quality Principles

- **Accuracy:** Data correctly represents the real-world operational event it records.
- **Completeness:** All necessary dataset components are present without omission.
- **Consistency:** Metrics align across various systems, business units, and report interfaces.
- **Timeliness:** Updates occur within the required reporting cadence and operational windows.

Acronym Reference

- **ERP:** Enterprise Resource Planning
- **SAP FI-CO:** Financial Accounting & Controlling
- **SAP SD:** Sales & Distribution
- **SAP MM:** Materials Management
- **BI / DWH:** Business Intelligence / Data Warehouse
- **UAT:** User Acceptance Testing