|--|

Tag table_1 [13]

PLC tags

PLC tags										
	Name	Data type	Address	Retain	sible from HMI/O	ble	ble in HMI engi-	Supervision	Comment	
1	ESO	Bool	%10.0	False	True	True	True		NC	
1	S ON (M)	Bool	%I0.1	False	True	True	True		Mill Switch NO	
1	S OFF	Bool	%10.3	False	True	True	True		NC	
•	F (M)	Bool	%10.4	False	True	True	True		Mill Relay NC	
•	F (E)	Bool	%10.5	False	True	True	True		Ext Relay NC	
-	Q (M)	Bool	%Q0.0	False	True	True	True		Milling Motor Contactor	
	Q (E)	Bool	%Q0.1	False	True	True	True		Extraction Motor Contactor	
1	P (M)	Bool	%Q0.2	False	True	True	True		Milling Working Lamp	
1	P (E)	Bool	%Q0.3	False	True	True	True		Extraction Working Lamp	
1	P (F)	Bool	%Q0.4	False	True	True	True		Fault Lamp	
1	S ON (E)	Bool	%10.2	False	True	True	True		Ext Switch NO	
1	S Reset	Bool	%10.6	False	True	True	True		Reset ESO	
1	F Reset	Bool	%Q0.5	False	True	True	True		Hold reset	

Totally Integrated Automation Portal											
Tag table_1 [13]											
User constants											
User constants		ata tama	Value	Camana							
Name	U	ata type	Value	Comm	ent						