





Design

Process



1. Cart is in ideal condition; no work is done. The rotavator is above the ground level and the bearing is locked at the upward position. Similarly, the leveller is above the ground and no process is taking place.

2. The rotavator is lowered from its home position for the tilling process. The bearing is mechanically locked at the lowest position so that the rotavator blades go deep inside the field.

3. The leveller is lowered as well to level the field after the field is tilled with the help of rotavator. It is a simultaneous process tilling and levelling.

4. The differential is connected with the rotavator shaft to provide rotary motion and with the help of this rotary motion the battery is also charged simultaneously.