




UNIVERSITY OF ENGINEERING AND TECHNOLOGY MARDAN

NAME	RIFAQ AJMAL
REG NO	23MDBC435
SECTION	A
DEPPT	COMPUTER SCIENCE
SUBJECT	DLD LAB
TEACHER	DR. SHEHZAD SIR

LAB TASK : 5

Even Parity

Even parity is a method used to detect errors in data transmission. In even parity, the number of bits set to 1 in a group of bits is made even by adding a parity bit.



Lab No. 5

LAB WORK

Even Parity

A	B	C	P
0	0	0	0
0	0	1	1
0	1	0	1
0	1	1	0
1	0	0	1
1	0	1	0
1	1	0	0
1	1	1	1

$$A \oplus B \oplus C$$

A input from A7

B from A6

C from A5

The output is on L2
for

A	B	C
1	0	0
0	1	0
0	1	1

= 1 led is on

= 1 led is on

= 0 led is off

Odd Parity

Odd parity, like even, parity is used to detect errors in data transmission. However, in odd parity the total number of bits set to 1, including the parity bit set to 1 is made odd.

Lab Work → For Odd Parity

We will add a not gate to this output of Even parity generator

$$\overline{A \oplus B \oplus C}$$

A from A5


B from A6

C from A7

output on L2

For

A	B	C	Output Odd Parity
0	0	0	1
0	0	1	0
0	1	0	0
0	1	1	1
1	0	0	0
1	0	1	1
1	1	0	1
1	1	1	0



THE END