Periodic Safety Update Report

ImagingRing m — extract: PMS information (b) to (d), MDCG 2022-21 Annex I

Cover page item	Entry
Manufacturer	medPhoton GmbH (SRN AT-MF-000002648)
Medical device(s) covered	ImagingRing m — Basic UDI-DI 1912007532IRm33; 4 UDI-DIs; Class IIb; EMDN Z11039009 FLUOROSCOPY DEVICES
Notified body	NB 0483 — certificate D4005200012
PSUR reference number / version	[manufacturer]
Data collection period	2025-10-08 to 2026-10-08

Post-Market Surveillance: information including general PMCF information

b) Scientific literature review of relevant specialist or technical literature

A literature search was performed on 2026-10-08 in PubMed/MEDLINE, Europe PMC and Crossref for records first available between 2025-10-08 and 2026-10-08, using a structured search for the device type, its synonyms and subject headings (full search strings in the search documentation). 2200 records were screened on title and abstract; 415 met the inclusion criteria (the device type is a subject of the publication and safety, performance or clinical-use findings are reported), of which 107 report safety-related findings. Publications concerning the device(s) covered by this PSUR: 0.

#	Publication	Finding type
1	Rettig N et al. (2026). Query-based prediction of 3D x-ray scatter fields in an interventional suite using a transformer model. Journal of radiological protection.	Safety
2	Schneider C et al. (2026). Angio-CT does not increase patient radiation exposure compared to conventional cone-beam CT for intra-arterial liver procedures. European radiology.	Safety
3	Sari S et al. (2026). Radiation Exposure in Elective Endovascular Carotid Artery Stenting. Clinical neuroradiology.	Safety
4	Hyvärinen T et al. (2026). Tight collimation substantially increases air kerma rate and decreases image contrast during selected fluoroscopy procedures. Physica medica.	Safety
5	Ishibashi T et al. (2026). Effects of the Institutional Volume of Endovascular Treatment for Lower Extremity Artery Disease on Radiation Exposure. Journal of endovascular therapy.	Safety
6	Yoon J et al. (2026). Basal cell carcinoma and squamous cell carcinoma of the hands in an orthopedic surgeon with occupational radiation exposure from C-arm fluoroscopy in Korea: a case report. Annals of occupational and environmental medicine.	Safety

Table continues: 409 further publications.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

c) Public databases and/or registry data

Database reviewed	Type	Period	Similar devices: findings
FDA MAUDE (USA)	Adverse event reports	2025-10-08 – 2026-10-08	636 reports (death 1, injury 3, malfunction 632); product code OWB; brands of this device type only
FDA Medical Device Recalls (USA)	Field safety corrective actions	5 years to 2026-10-08	3 recall events, 3 in the data collection period
Health Canada Recalls and Safety Alerts	Field safety corrective actions	5 years	3 recalls
MHRA Field Safety Notices (UK)	Field safety notices	5 years	37 notices
EUDAMED (EU)	Device registration	at 2026-10-08	56 UDI-DIs registered under EMDN Z11039009

Most frequent device problems, similar devices (FDA MAUDE)	Reports
Failure to Advance	301
Incorrect, Inadequate or Imprecise Result or Readings	87
Application Program Freezes or Fails to Launch	83
Mechanical Problem	83
Image Display Error/Artifact	68

Most frequent health effects, similar devices (FDA MAUDE)	Reports
Spinal Column Injury	2
Bone Fracture(s)	1
Pain	1
Perforation	1

98% of the MAUDE reports for similar devices in the period were submitted by one manufacturer (Medtronic Navigation Boxborough); year-on-year changes mainly reflect that manufacturer's reporting. Reports concerning the device(s) covered by this PSUR are excluded from these figures.

Date	Firm / authority	Field action (excerpt)
2026-08-04	Canon Medical System, USA, INC.	Due to the fixing screws of ceiling movement gear in ceiling suspended arm that are part of the X-ray interventional systems may become loose.
2026-05-19	Medtronic Navigation, Inc.-Boxborough	Potential for image artifacts caused by an anomaly in the O-arm O2 Imaging System s detector panel firmware.
2025-12-19	Canon Medical System, USA, INC.	It has been discovered that there is a possibility that the fixing screws of the ceiling movement gear in the ceiling suspended arm that are part of the X-ray …
2026-09-09	Health Canada	Veradius Unity and BV Pulsera Mobile C-Arm System-9in. and 12in. Versions
2024-12-18	Health Canada	OEC Elite and OEC Mobile C-arms
2026-09-03	Philips	BV Endura, BV Pulsera, BV Vectra, Veradius, Zenition
2026-08-18	Philips	Azurion systems

Registries: no device registry with public device-level data was identified for this device type.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

d) Publicly available information about similar medical devices

Similar devices are those registered under EMDN Z11039009 (FLUOROSCOPY DEVICES) and, for third-country data, FDA product code OWB. In EUDAMED, 14 other manufacturers were identified in a sample of 52 registrations. In the USA, 1 new similar device received 510(k) clearance in the period; the 510(k) summaries describe indications for use and performance testing.

Decision	510(k)	Applicant	Device
2025-11-04	K250241	Siemens Medical Solutions USA, Inc.	Cios Select

Manufacturer of similar devices (EU market)	Country
GENORAY CO., Ltd.	South Korea
Siemens Healthcare GmbH	Germany
Philips Medical Systems DMC GmbH	Germany
Beijing Wandong Medical Technology Co., Ltd.	China

Summary of safety and clinical performance (SS(C)P): not applicable — the device is Class IIb and non-implantable (MDR Art. 32).

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].