Periodic Safety Update Report

Fortress Introducer Sheath System — extract: PMS information (b) to (d), MDCG 2022-21 Annex I

Cover page item	Entry
Manufacturer	Contract Medical International GmbH (SRN DE-MF-000007409)
Medical device(s) covered	Fortress Introducer Sheath System — Basic UDI-DI 4251244500000113F; 23 UDI-DIs; Class IIa; EMDN C0502 CARDIOVASCULAR INTRODUCER SHEATHS, VALVED
Notified body	NB 0344 — certificate 2254506CE03
PSUR reference number / version	[manufacturer]
Data collection period	2024-10-07 to 2026-10-08

Post-Market Surveillance: information including general PMCF information

b) Scientific literature review of relevant specialist or technical literature

A literature search was performed on 2026-10-08 in PubMed/MEDLINE, Europe PMC and Crossref for records first available between 2024-10-07 and 2026-10-08, using a structured search for the device type, its synonyms and subject headings (full search strings in the search documentation). 917 records were screened on title and abstract; 72 met the inclusion criteria (the device type is a subject of the publication and safety, performance or clinical-use findings are reported), of which 41 report safety-related findings. Publications concerning the device(s) covered by this PSUR: 0.

#	Publication	Finding type
1	Isomura S et al. (2026). Bailout of long-sheath tip separation during noncontrast transfemoral transcatheter aortic valve replacement. JTCVS structural and endovascular.	Safety
2	Deng G et al. (2026). Impact of spasmolytic cocktail and Glidesheath Slender on radial artery spasm in transradial cerebral angiography: A randomized factorial trial. Journal of vascular and interventional radiology.	Safety
3	Chan EIA et al. (2026). Sheath-to-Artery Diameter Ratio: A Robust Predictor of Early Access-Site Adverse Events in Percutaneous Procedures. Catheterization and cardiovascular interventions.	Safety
4	Mizukami A et al. (2026). Fogarty Catheter Removal of External Iliac Artery Thrombus Caused by Sheath-Related Thrombus Entrapment Following Mechanical Thrombectomy: A Case Report. Journal of neuroendovascular therapy.	Safety
5	Jo J et al. (2026). Feasibility of Distal Radial Access in the Use of a Large-Bore Sheath for Percutaneous Coronary Intervention: Real-World Evidence From the Nationwide Cohort. Korean circulation journal.	Safety
6	Luo B et al. (2026). Bidirectional Retrieval of a Fractured Femoral Venous Sheath. JACC. Case reports.	Safety

Table continues: 66 further publications.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

c) Public databases and/or registry data

Database reviewed	Type	Period	Similar devices: findings
FDA MAUDE (USA)	Adverse event reports	2024-10-07 – 2026-10-08	6,089 reports (death 179, injury 1,717, malfunction 4,179); product code DYB; brands of this device type only
FDA Medical Device Recalls (USA)	Field safety corrective actions	5 years to 2026-10-08	27 recall events, 9 in the data collection period
Health Canada Recalls and Safety Alerts	Field safety corrective actions	5 years	12 recalls
MHRA Field Safety Notices (UK)	Field safety notices	5 years	6 notices
EUDAMED (EU)	Device registration	at 2026-10-08	2,641 UDI-DIs registered under EMDN C0502

Most frequent device problems, similar devices (FDA MAUDE)	Reports
Gas/Air Leak	1,159
Fluid/Blood Leak	1,007
Adverse Event Without Identified Device or Use Problem	761
Material Split, Cut or Torn	760
Patient Device Interaction Problem	382

Most frequent health effects, similar devices (FDA MAUDE)	Reports
Vascular Dissection	421
Hemorrhage/Blood Loss/Bleeding	396
Perforation of Vessels	230
Hematoma	141

Date	Firm / authority	Field action (excerpt)
2026-06-15	Terumo Medical Corporation	Product was packaged with the 0.025 guidewire instead of the 0.021 guidewire.
2026-06-11	Abiomed, Inc.	A potential for introducer sheath leakage from under the sheath cap and along the hub score lines, identified in 14Fr and 23Fr Introducers. These manufacturing …
2026-06-10	Oscor Inc.	Due to manufacturing issues, there is a potential for the 14Fr and 23Fr introducer sheaths to leak from the sidearm, under the sheath cap, and along the hub …
2026-07-02	Health Canada	Glidesheath Slender® Introducer Sheath
2026-06-29	Health Canada	Abiomed Introducer Kits with Impella Heart Pumps
2026-08-11	Oscor	Introducer Kit for Impella distributed within the Abiomed Impella 14 Fr and 23 Fr Introducer Kits
2026-02-24	Merit Medical	16F Dual-Valved Splittable Sheath Introducer

Registries: no device registry with public device-level data was identified for this device type.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

d) Publicly available information about similar medical devices

Similar devices are those registered under EMDN C0502 (CARDIOVASCULAR INTRODUCER SHEATHS, VALVED) and, for third-country data, FDA product code DYB. In EUDAMED, 8 other manufacturers were identified in a sample of 300 registrations. In the USA, 25 new similar devices received 510(k) clearance in the period; the 510(k) summaries describe indications for use and performance testing.

Decision	510(k)	Applicant	Device
2026-07-29	K253526	Medline Industries, LP	NAMIC Dilator and Sheath
2026-07-06	K261529	Hartman Medical Group, LLC	Micropuncture Kit / Micropuncture Access Kit / Micropuncture Introducer Set/ Microintroducer Kit / Microintrod
2026-06-22	K261950	Health Line International Corporation	Health Line Tearaway Introducer
2026-06-05	K261492	CenterPoint Systems, LLC	FieldFlex Steerable Sheath

Manufacturer of similar devices (EU market)	Country
Zhejiang Barty Medical Technology Co., Ltd.	China
W. L. Gore & Associates, Inc.	United States
APT Medical Inc.	China
Arrow International LLC (Subsidiary of Teleflex Incorporated)	United States

Summary of safety and clinical performance (SS(C)P): not applicable — the device is Class IIa and non-implantable (MDR Art. 32).

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].