Periodic Safety Update Report

Poseidon URO Guide Wire — extract: PMS information (b) to (d), MDCG 2022-21 Annex I

Cover page item	Entry
Manufacturer	SP Medical A/S (SRN DK-MF-000019782)
Medical device(s) covered	Poseidon URO Guide Wire — Basic UDI-DI 5710086-GWPUMD; 1 UDI-DI; Class IIa; EMDN U0601 UROLOGICAL GUIDEWIRES, HYDROPHILIC
Notified body	NB 0197 — certificate HZ 2320977-1
PSUR reference number / version	[manufacturer]
Data collection period	2024-10-07 to 2026-10-08

Post-Market Surveillance: information including general PMCF information

b) Scientific literature review of relevant specialist or technical literature

A literature search was performed on 2026-10-08 in PubMed/MEDLINE, Europe PMC and Crossref for records first available between 2024-10-07 and 2026-10-08, using a structured search for the device type, its synonyms and subject headings (full search strings in the search documentation). 496 records were screened on title and abstract; 17 met the inclusion criteria (the device type is a subject of the publication and safety, performance or clinical-use findings are reported), of which 4 report safety-related findings. Publications concerning the device(s) covered by this PSUR: 0.

#	Publication	Finding type
1	Patil AA et al. (2025). Knotting of Guide Wires During Percutaneous Nephrolithotomy: A Complex Intraoperative Challenge. Cureus.	Safety
2	Giannakas T et al. (2025). Retained Intrarenal Guidewire Fragment After Endourological Stone Surgery: Antegrade Percutaneous Snare Retrieval and Literature Review. Reports (MDPI).	Safety
3	Orecchia L et al. (2025). IP08-39 ARE HYDROPHILIC GUIDEWIRES SAFE TO PASS THROUGH a METALLIC NEEDLE DURING PCNL? RESULTS FROM a LABORATORY STRESS TEST. Journal of Urology.	Safety
4	Para S et al. (2025). Retrieval of Knotted and Stripped Guidewires Lost During Percutaneous Intervention on Kidney—A Case Series and Review of Literature. Urology Research and Practice.	Safety
5	Deligiannis P et al. (2026). Fluoroscopy-guided transurethral resection with antegrade guidewire assistance for retrieval of a buried double-J stent: A case report. World journal of clinical cases.	Performance
6	Bashi T et al. (2026). Transfer of a Guidewire Alongside a Nephrostomy Tube in Patients Undergoing Endourological Procedures. Journal of endourology.	Performance

Table continues: 11 further publications.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

c) Public databases and/or registry data

Database reviewed	Type	Period	Similar devices: findings
FDA MAUDE (USA)	Adverse event reports	2024-10-07 – 2026-10-08	65 reports (death 0, injury 4, malfunction 61); product code OCY; brands of this device type only
FDA Medical Device Recalls (USA)	Field safety corrective actions	5 years to 2026-10-08	1 recall event, 0 in the data collection period
Health Canada Recalls and Safety Alerts	Field safety corrective actions	5 years	0 recalls
MHRA Field Safety Notices (UK)	Field safety notices	5 years	0 notices
EUDAMED (EU)	Device registration	at 2026-10-08	1,045 UDI-DIs registered under EMDN U0601

Most frequent device problems, similar devices (FDA MAUDE)	Reports
Peeled/Delaminated	27
Material Separation	16
Break	8
Unsealed Device Packaging	5
Unraveled Material	4

Most frequent health effects, similar devices (FDA MAUDE)	Reports
Foreign Body In Patient	4

100% of the MAUDE reports for similar devices in the period were submitted by one manufacturer (Cook); year-on-year changes mainly reflect that manufacturer's reporting. Reports concerning the device(s) covered by this PSUR are excluded from these figures.

Date	Firm / authority	Field action (excerpt)
2022-08-16	Cook Incorporated	Cook Medical identified that devices from the affected device lots may have a complete breach of the chevron seal of the packaging. Therefore, the sterility of …

Registries: no device registry with public device-level data was identified for this device type.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

d) Publicly available information about similar medical devices

Similar devices are those registered under EMDN U0601 (UROLOGICAL GUIDEWIRES, HYDROPHILIC) and, for third-country data, FDA product code OCY. In EUDAMED, 16 other manufacturers were identified in a sample of 300 registrations. In the USA, no new similar devices received 510(k) clearance in the period.

Manufacturer of similar devices (EU market)	Country
Zhejiang YiGao Medical Technology Co., Ltd.	China
Alton (Shanghai) Medical Instruments Co., Ltd.	China
MicroPort Urocare (Jiaxing) Co.,Ltd.	China
Gyrus ACMI, Inc.	United States

Summary of safety and clinical performance (SS(C)P): not applicable — the device is Class IIa and non-implantable (MDR Art. 32).

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].