# Periodic Safety Update Report

Autra 55 — extract: PMS information (b) to (d), MDCG 2022-21 Annex I

| Cover page item | Entry |
|---|---|
| Manufacturer | SONOSCAPE MEDICAL CORP. (SRN CN-MF-000009623) |
| Medical device(s) covered | Autra 55 — Basic UDI-DI 69458686U1030SG; 28 UDI-DIs; Class IIa; EMDN Z11040104 MULTIDISCIPLINARY ULTRASOUND SCANNERS (INTERNAL AND CARDIOLOGY, ETC.) |
| Notified body | NB 0197 — certificate HZ 2027206-1 |
| PSUR reference number / version | [manufacturer] |
| Data collection period | 2024-10-07 to 2026-10-08 |

## Post-Market Surveillance: information including general PMCF information

### b) Scientific literature review of relevant specialist or technical literature

A literature search was performed on 2026-10-08 in PubMed/MEDLINE, Europe PMC and Crossref for records first available between 2024-10-07 and 2026-10-08, using a structured search for the device type, its synonyms and subject headings (full search strings in the search documentation). 2559 records were screened on title and abstract; 366 met the inclusion criteria (the device type is a subject of the publication and safety, performance or clinical-use findings are reported), of which 50 report safety-related findings. Publications concerning the device(s) covered by this PSUR: 0.

| # | Publication | Finding type |
|---|---|---|
| 1 | Jerry J et al. (2026). Closing the gap in ultrasound probe hygiene: Improving ultrasound probe decontamination through evidence-based interventions. Ultrasound (Leeds, England). | Safety |
| 2 | Hu B et al. (2026). Quantum-edge synergy for dynamic acoustic compensation in ultrasound safety: a narrative review of tissue heterogeneity challenges. Frontiers in medical technology. | Safety |
| 3 | Sasanuma H et al. (2026). Safety and Bioeffects of Acoustic Radiation Force Impulse (ARFI) in Ultrasound Elastography: A Narrative Review. Ultrasound in medicine & biology. | Safety |
| 4 | Rutala WA et al. (2026). New developments in processing semicritical items: Channeled endoscopes, probes, optical and nasal devices, and others. American journal of infection control. | Safety |
| 5 | McMullen K et al. (2026). Implementation of a novel modality for manual high-level disinfection of ultrasound probes: User perceptions and application compliance. American journal of infection control. | Safety |
| 6 | Mann R et al. (2026). Microscopic Topography of Ultrasound Probes: Implications for High-Level Disinfection and Infection Control. Biomedical instrumentation & technology. | Safety |

*Table continues: 360 further publications.*

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

### c) Public databases and/or registry data

| Database reviewed | Type | Period | Similar devices: findings |
|---|---|---|---|
| FDA MAUDE (USA) | Adverse event reports | 2024-10-07 – 2026-10-08 | 3,237 reports (death 15, injury 135, malfunction 3,083); product code IYN, IYO, ITX |
| FDA Medical Device Recalls (USA) | Field safety corrective actions | 5 years to 2026-10-08 | 8 recall events, 8 in the data collection period |
| Health Canada Recalls and Safety Alerts | Field safety corrective actions | 5 years | 13 recalls |
| MHRA Field Safety Notices (UK) | Field safety notices | 5 years | 15 notices |
| EUDAMED (EU) | Device registration | at 2026-10-08 | 1,695 UDI-DIs registered under EMDN Z11040104 |

| Most frequent device problems, similar devices (FDA MAUDE) | Reports |
|---|---|
| Poor Quality Image | 1,143 |
| No Apparent Adverse Event | 244 |
| Unintended System Motion | 199 |
| Break | 186 |
| Material Integrity Problem | 155 |

| Most frequent health effects, similar devices (FDA MAUDE) | Reports |
|---|---|
| Perforation | 18 |
| Laceration(s) | 14 |
| Electric Shock | 9 |
| Pain | 9 |

| Date | Firm / authority | Field action (excerpt) |
|---|---|---|
| 2026-08-07 | Philips Ultrasound, LLC | Due to software issue with ultrasound system, doppler sample is displayed shallower than its actual measurement location, potentially causing inaccurate blood … |
| 2025-11-17 | Sheathing Technologies Inc | Vaginal/rectal ultrasound probe covers with a viral barrier may have product defects, which may result in contamination during use, posing an infection risk. |
| 2025-10-31 | Philips Ultrasound, LLC | Ultrasound system compatibility issues with Apple devices running iOS 18 may cause a failure to perform live imagining. |
| 2025-10-30 | Health Canada | BK Medical Ultrasound Systems |
| 2024-09-19 | Health Canada | Bk3000/3500, Bk5000 and Bkactiv Ultrasound Systems |
| 2026-08-18 | Philips | EPIQ Elite Diagnostic Ultrasound system |
| 2025-11-24 | BK Medical ApS | Ultrasound system type 2300, 1300, 1202 |

Registries: no device registry with public device-level data was identified for this device type.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

## d) Publicly available information about similar medical devices

Similar devices are those registered under EMDN Z11040104 (MULTIDISCIPLINARY ULTRASOUND SCANNERS (INTERNAL AND CARDIOLOGY, ETC.)) and, for third-country data, FDA product code IYN, IYO, ITX. In EUDAMED, 11 other manufacturers were identified in a sample of 300 registrations. In the USA, 97 new similar devices received 510(k) clearance in the period; the 510(k) summaries describe indications for use and performance testing.

| Decision | 510(k) | Applicant | Device |
|---|---|---|---|
| 2026-09-25 | K262548 | Philips Ultrasound, LLC | EPIQ Inspira Series Diagnostic Ultrasound System; Affiniti Series Diagnostic Ultrasound System |
| 2026-09-25 | K263182 | Samsung Medison Co., Ltd. | EVO X30 Diagnostic Ultrasound System; EVO X20 Diagnostic Ultrasound System; EVO X10 Diagnostic Ultrasound Syst |
| 2026-09-24 | K260313 | MEDA Co., Ltd. | MD-6000S Bladder Scanner |
| 2026-09-24 | K260114 | CIVCO Medical Instruments Co., Inc. | Align® Cover and Pad Guidance Tool |

| Manufacturer of similar devices (EU market) | Country |
|---|---|
| Shenzhen Mindray Bio-Medical Electronics Co., Ltd. | China |
| VINNO Technology (Suzhou) Co., Ltd. | China |
| Wuhan United Imaging Healthcare Co., Ltd. | China |
| FUJIFILM Corporation | Japan |

Summary of safety and clinical performance (SS(C)P): not applicable — the device is Class IIa and non-implantable (MDR Art. 32).

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].