Periodic Safety Update Report

VECTOR — extract: PMS information (b) to (d), MDCG 2022-21 Annex I

Cover page item	Entry
Manufacturer	DÜRR DENTAL SE (SRN DE-MF-000006032)
Medical device(s) covered	VECTOR — Basic UDI-DI ++E2471011XR; 3 UDI-DIs; Class IIa; EMDN Z12119007 DENTAL PROPHYLAXIS EQUIPMENT
Notified body	NB 0297 — certificate 1000275872
PSUR reference number / version	[manufacturer]
Data collection period	2024-10-07 to 2026-10-08

Post-Market Surveillance: information including general PMCF information

b) Scientific literature review of relevant specialist or technical literature

A literature search was performed on 2026-10-08 in PubMed/MEDLINE, Europe PMC and Crossref for records first available between 2024-10-07 and 2026-10-08, using a structured search for the device type, its synonyms and subject headings (full search strings in the search documentation). 646 records were screened on title and abstract; 90 met the inclusion criteria (the device type is a subject of the publication and safety, performance or clinical-use findings are reported), of which 44 report safety-related findings. Publications concerning the device(s) covered by this PSUR: 0.

#	Publication	Finding type
1	Alhumaidan A et al. (2026). Effect of different scaling instruments on the roughness of esthetic resin composite restorations: an in vitro study. Frontiers in dental medicine.	Safety
2	Krapež J et al. (2026). Damage of irradiated teeth by ultrasonic scaling: an in vitro study. Supportive care in cancer.	Safety
3	Jin Y et al. (2026). Linking oral microbiota to clinic air during ultrasonic scaling: Quantitative sequencing and CFD modeling reveal pathogenic aerosol emissions, infection risk, and control strategies. Environmental pollution (Barking, Essex.	Safety
4	Moeller J et al. (2026). Influence of Air Polishing and Ultrasonics on Veneer Margins in Vitro: An Optical Coherence Tomography Pilot Study. Clinical and experimental dental research.	Safety
5	Sagmak S et al. (2026). Comparative effects of air-polishing and conventional prophylaxis methods on surface roughness and gloss of composite restorations. BMC oral health.	Safety
6	Law B et al. (2026). Extensive Cervicofacial and Mediastinal Emphysema Following Subgingival Air-Polishing for Peri-Implantitis: A Case Report. Australian dental journal.	Safety

Table continues: 84 further publications.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

c) Public databases and/or registry data

Database reviewed	Type	Period	Similar devices: findings
FDA MAUDE (USA)	Adverse event reports	2024-10-07 – 2026-10-08	349 reports (death 0, injury 5, malfunction 344); product code ELC; brands of this device type only
FDA Medical Device Recalls (USA)	Field safety corrective actions	5 years to 2026-10-08	2 recall events, 0 in the data collection period
Health Canada Recalls and Safety Alerts	Field safety corrective actions	5 years	1 recall
MHRA Field Safety Notices (UK)	Field safety notices	5 years	1 notice
EUDAMED (EU)	Device registration	at 2026-10-08	42 UDI-DIs registered under EMDN Z12119007

Most frequent device problems, similar devices (FDA MAUDE)	Reports
No Flow	138
Restricted Flow rate	134
Overheating of Device	93
Break	51
Adverse Event Without Identified Device or Use Problem	2

Most frequent health effects, similar devices (FDA MAUDE)	Reports
Burn(s)	6
Electric Shock	2
Device Embedded In Tissue or Plaque	1
Foreign Body In Patient	1

82% of the MAUDE reports for similar devices in the period were submitted by one manufacturer (Dentsply); year-on-year changes mainly reflect that manufacturer's reporting. Reports concerning the device(s) covered by this PSUR are excluded from these figures.

Date	Firm / authority	Field action (excerpt)
2024-05-30	Dental EZ Group Star Dental Division	Tip holder portion of the scaler tip assembly may have an oversized condition that will not allow the scaler tip to stay seated in the holder may cause injury
2024-03-13	Electro Medical Systems SA	Received complaints that bottles assembled with one batch of bottle collars can be disassembled in two parts when used under pressure (during treatment or …
2024-07-18	Health Canada	Titan Blis-Sonic SW Scaler
2024-02-27	EMS	NIGHT CLEANER Bottle, PIEZON Bottle, WATER Bottle

Registries: no device registry with public device-level data was identified for this device type.

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].

d) Publicly available information about similar medical devices

Similar devices are those registered under EMDN Z12119007 (DENTAL PROPHYLAXIS EQUIPMENT) and, for third-country data, FDA product code ELC. In EUDAMED, 5 other manufacturers were identified in a sample of 17 registrations. In the USA, 2 new similar devices received 510(k) clearance in the period; the 510(k) summaries describe indications for use and performance testing.

Decision	510(k)	Applicant	Device
2026-01-28	K253254	E.M.S Electro Medical Systems S.A	GBT Machine Airflow Prophylaxis Master
2025-09-19	K251689	Nakanishi, Inc.	VARIOS 170 LUX SCALER SYSTEM (VA170LUXS10); VARIOS 170 LUX SCALER SYSTEM (VA170LUXS11); VARIOS 170 SCALER SYST

Manufacturer of similar devices (EU market)	Country
Nakanishi Inc.	Japan
President Dental GmbH	Germany
Pascal Company Inc.	United States
Prime Dental Manufacturing	United States

Summary of safety and clinical performance (SS(C)P): not applicable — the device is Class IIa and non-implantable (MDR Art. 32).

Manufacturer's assessment against the risk management file and clinical evaluation: [to be completed by the manufacturer].