



Facility Maintenance Report

Work order WO-2026-0317 · Reporting window: 8–12 June 2026

8 Jun 2026 · 08:00

Scheduled preventive maintenance — zone A

Technicians

Alex Rivera
Jordan Lee

Total hours

Equipment

4 h Air handler AH-10
3 h Conveyor C-3

7 h

Parts

2 h	Intake filter (set)	\$45.00
1 h	Drive belt	\$32.00
	Sealant cartridge	\$9.00
	Parts total	\$86.00

Tasks performed

- Inspected the air handler and replaced intake filters
- Lubricated conveyor bearings and checked belt tension
- Calibrated temperature sensors in cold storage
- Tested emergency lighting and replaced two ballasts

Notes

Follow-up recommended: order a replacement bearing for the next cycle.

Technician signature

9 Jun 2026 · 08:30

Scheduled preventive maintenance — zone B

Technicians

Sam Patel
Casey Morgan

Total hours

Equipment

5 h Air handler AH-11
4 h Conveyor C-4

8 h


Parts

3 h	Intake filter (set)	\$45.00
2 h	Drive belt	\$32.00
	Sealant cartridge	\$9.00
	Parts total	\$86.00

Tasks performed

- Lubricated conveyor bearings and checked belt tension
- Calibrated temperature sensors in cold storage
- Tested emergency lighting and replaced two ballasts
- Cleared the condensate drain and flushed the line

Photos



Technician signature



10 Jun 2026 · 08:00

Scheduled preventive maintenance — zone C

Technicians

Jordan Lee
Drew Nguyen

Total hours

Equipment

6 h Air handler AH-12
3 h Conveyor C-5

9 h

Parts



4 h Intake filter (set) \$45.00
1 h Drive belt \$32.00
Sealant cartridge \$9.00

Parts total \$86.00

Tasks performed

- Calibrated temperature sensors in cold storage
- Tested emergency lighting and replaced two ballasts
- Cleared the condensate drain and flushed the line
- Verified fire-suppression pressure gauges

Photos



Technician signature



11 Jun 2026 · 08:30

Scheduled preventive maintenance — zone D

Technicians

Casey Morgan
Alex Rivera

Total hours

4 h
4 h
10 h

Equipment

Air handler AH-13
Conveyor C-6

Parts

2 h	Intake filter (set)	\$45.00
2 h	Drive belt	\$32.00
	Sealant cartridge	\$9.00
	Parts total	\$86.00



Tasks performed

- Tested emergency lighting and replaced two ballasts
- Cleared the condensate drain and flushed the line
- Verified fire-suppression pressure gauges
- Tightened electrical-panel connections and logged readings

Notes

Follow-up recommended: order a replacement bearing for the next cycle.

Photos



Technician signature

12 Jun 2026 · 08:00

Scheduled preventive maintenance — zone A

Technicians

Drew Nguyen
Sam Patel

Total hours

5 h
3 h
7 h

Equipment

Air handler AH-14
Conveyor C-7

Parts

3 h	Intake filter (set)	\$45.00
1 h	Drive belt	\$32.00
	Sealant cartridge	\$9.00
	Parts total	\$86.00

Tasks performed

- Cleared the condensate drain and flushed the line
- Verified fire-suppression pressure gauges
- Tightened electrical-panel connections and logged readings
- Replaced worn gaskets on the pump housing

Technician signature



8 Jun 2026 · 08:30

Scheduled preventive maintenance — zone B

Technicians

Alex Rivera
Jordan Lee

Total hours

Equipment

6 h Air handler AH-15
4 h Conveyor C-3

8 h

Parts


4 h	Intake filter (set)	\$45.00
2 h	Drive belt	\$32.00
	Sealant cartridge	\$9.00

Parts total **\$86.00**

Tasks performed

- Verified fire-suppression pressure gauges
- Tightened electrical-panel connections and logged readings
- Replaced worn gaskets on the pump housing
- Inspected the air handler and replaced intake filters

Photos



Technician signature



9 Jun 2026 · 08:00

Scheduled preventive maintenance — zone C

Technicians

Sam Patel
Casey Morgan

Total hours

Equipment

4 h Air handler AH-16
3 h Conveyor C-4

9 h

Parts

2 h Intake filter (set) \$45.00
1 h Drive belt \$32.00
Sealant cartridge \$9.00

Parts total \$86.00



Tasks performed

- Tightened electrical-panel connections and logged readings
- Replaced worn gaskets on the pump housing
- Inspected the air handler and replaced intake filters
- Lubricated conveyor bearings and checked belt tension

Notes

Follow-up recommended: order a replacement bearing for the next cycle.

Photos



Technician signature