
Homework 6: Nuclear Propulsion

Riley J. Kyle



Answers:

$x_{T_{max}} =$

$Q \doteq$

$F =$

$I_{sp} =$

Conditions for sin power density distribution.

1) zero slope of T_t at $x = 0$
2) max slope of T_t at $x = L/2$
3) zero slope of T_t at $x = L$

Additionally $T_s \rightarrow T_w$ occurs at some x between $x = L/2$ and $x = L$.

$$\sum_{i=1}^{n} 2n - 1 \tag{1}$$