



THE 40-CFR-84 TACTICAL SURVIVAL MANUAL

"PRECISION IS THE ONLY DEFENSE." A STEP-BY-STEP
FIELD DIRECTIVE FOR THE JAN 01 TRANSITION.

OPERATION CONVAIR



PHASE 1: THE ZERO-HOUR WEIGHT

[DIRECTIVE] :

BY 23:59 ON DECEMBER 31, EVERY HFC CYLINDER IN YOUR FLEET MUST HAVE A "TRUE-ZERO" WEIGHT RECORDED. THE EPA TREATS UNACCOUNTED GAS AS "ILLEGAL VENTING."

OPERATIONAL PROTOCOL] :

- IDENTIFY: TAG EVERY CYLINDER (R-410A, R-134A, R-404A).
- WEIGH: RECORD THE TOTAL WEIGHT (GROSS) VS. TARE WEIGHT.
- LOG: ENTER THESE INTO THE TRUE608 "INITIAL DEPLOYMENT" TAB ON JAN 01.
- VERIFY: IF A CYLINDER IS MISSING A TAG, IT DOES NOT EXIST IN THE EYES OF AN AUDITOR.



PHASE 2: PERSONNEL CREDENTIALS

[RISK ASSESSMENT] :

A608-CERTIFICATION IS NOT A SUGGESTION; IT IS A LICENSE TO OPERATE FEDERAL ASSETS. AN EXPIRED CERT DURING A 2026 AUDIT DISQUALIFIES EVERY LOG THAT TECHNICIAN HAS TOUCHED.

[FIELD REQUIREMENTS] :

- **COLLECT: GATHER COPIES OF ALL TECHNICIAN 608 CARDS.**
- **AUDIT: CHECK EXPIRATION DATES.**
- **DIGITIZE: HAVE THESE READY TO UPLOAD INTO THE TRUE608 VAULT.**



PHASE 3: SHIELD INITIALIZATION

[OBJECTIVE]:

ON JANUARY 1ST, PAPER LOGS ARE RETIRED. ANY REFRIGERANT MOVEMENT AFTER 00:00 MUST BE ENCRYPTED.

[SEQUENCE OF ACTIVATION] :

- **LOG IN TO YOUR TRUE608 COMMAND CENTER.**
- **UPLOAD YOUR DEC 31 INVENTORY SNAPSHOT.**
- **ASSIGN YOUR TECHNICIANS TO THEIR DIGITAL SQUADS.**
- **GENERATE YOUR FIRST 2026 COMPLIANCE CERTIFICATE.**