

$T * \omega$	2	2	0	0	18	18	14	14
Index	1	2	3	4	5	6	7	8

$$MAX(T * \omega) = 18$$

$$PV_0(T * \omega) = \{2, 2, 14, 14, 18, 18\}$$

$$PPV_0(T * \omega) = 6/8 = 0.75$$

$$MPV_0(T * \omega) = \frac{2+2+14+14+18+18}{6} = 11.3$$

$$MIPV_0(T * \omega) = \frac{1+2+5+6+7+8}{6} = 4.83$$

$$LSPV_0(T * \omega) = \max\{2 - 1, 8 - 5\} + 1 = 4$$

$$PV_3(T * \omega) = \{14, 14, 18, 18\}$$

$$PPV_3(T * \omega) = 4/8 = 0.50$$

$$MPV_3(T * \omega) = \frac{14+14+18+18}{4} = 16$$

$$MIPV_3(T * \omega) = \frac{5+6+7+8}{4} = 6.5$$

$$LSPV_3(T * \omega) = (8 - 5) + 1 = 4$$