EX. NO. 2.1 CREATE A 3D SOLID MODEL FROM ISOMETRIC DRAWING.


AIM: To create a 3d model from the given isometric drawing using the Fusion 360 tool.

REQUIREMENTS:


1. Autodesk Fusion 360.
2. Windows 11.
3. 16 GB of RAM (integrated graphics recommended: 1 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload.

PROCEDURE:

1 .Select a new file and create a sketch. At first draw a rectangle of 100mm length and 50mm height. Finish the sketch and extrude it for 30mm.




2.Now again click create sketch and then add a circle of 50 diameter. Again, click finish sketch and extrude it for 20mm.




3. Now select the top view. Make a circle and a square there, and make sure the dimension of both is 15 mm, and then extrude it.

4. Finally, make a square of 30mm in the centre of the top view. Then extrude it to 10mm. Then click Chamfer, and then change the type from Equal Distance to Distance and Angle.




5. Then choose the distance as 30mm and the angle as 45deg. Then save the changes that are made by us. Then export it.

Sketches:



OUTPUT:



RESULT:

Thus, the 3D model is created from the given isometric drawing.