LMP of a material is given below. Find the Rupture time for the material at 50 MPa stress if exposed to 900K. Also find the reduction in life if the stress level is increased to 100MPa. **Marks)**

