Q.2. In a process industry, dry reagent powder is stored in a cylindrical tank of diameter 1m and height 2m. Suggest at least 3 sensing methods for detecting the amount of powder stored in the tank; with their main advantage and limitation. [4.5 Marks]