


I TYPE INSTRUCTION SHEET



OPCODE = 00100

Func

IMM – 12BITS

RS1 = X1-X31 RD = X1-X31

ADDI = 5'b000000;

SUBI = 5'b000001;

ORI = 5'b000010;

ANDI = 5'b000011;

XORI = 5'b000110;

SLLI = 5'b001110;

SRLI = 5'b100000;

SRAI = 5'b100001;