


R3I TYPE SHEET INSTRUCTIONS



OPCODE = 00011

FUNC

RS2 = X1-X32 REGISTER

RS1= X1-X32 REGISTE

ADD = 7'b00000000; // 0

RD = X1-X32 REGISTER

IMM= 5BITS SO

SUB = 7'b00000001; // 1

FROM 0-31 OR -16 TO

OR = 7'b00000010; // 2

+15

AND = 7'b00000011; // 3

NAND = 7'b00000100; // 4

NOR = 7'b00000101; // 5

XOR = 7'b00000110; // 6

XNOR = 7'b00000111; // 7

NOT_AND_XOR = 7'b0001001; // 9

NOT_OR_AND = 7'b0001010; // 10

AND_NOT2 = 7'b0001011; // 11

INC = 7'b0001100; // 12

DEC = 7'b0001101; // 13

MAX = 7'b0010011; // 19

MIN = 7'b0010100; // 20

MAC = 7'b0010101; // 21

MSC = 7'b0010110; // 22

