


R3 TYPE SHEET INSTRUCTIONS



OPCODE = 00010

FUNC

RS2 = X1-X32 REGISTER

RS1= X1-X32 REGISTE

ADD = 7'b00000000; // 0

RD = X1-X32 REGISTER

IMM= NOT USED

SUB = 7'b00000001; // 1

OR = 7'b00000010; // 2

AND = 7'b00000011; // 3

NAND = 7'b00000100; // 4

NOR = 7'b00000101; // 5

XOR = 7'b00000110; // 6

XNOR = 7'b00000111; // 7

AND_NOT = 7'b00111111; // 31

OR_NOT = 7'b01000000; // 32

INC = 7'b00001100; // 12

DEC = 7'b00001101; // 13

SLL = 7'b00001110; // 14

SLT = 7'b00001111; // 15

SRL = 7'b00100000; // 16

SRA = 7'b00100001; // 17

SGT = 7'b00100010; // 18

MAX = 7'b0010011; // 19
MIN = 7'b0010100; // 20
MUL = 7'b0010111; // 23
VADD8 = 7'b0011000; // 24
VMAX8 = 7'b0011001; // 25
SDOTP4 = 7'b0011010; // 26