

R2 MOV TYPE SHEET

FUNC


IMMEDIATE

RS1

RD

OPCODE

R2 TYPE



OPCODE = 01010

IMM NOT NEEDED

RS1=X1-X31 REGISTER

RD = X1-X31 REGISTER

FUNC

0000000 ONLY