

APPROVED WORK PERMIT

Permit ID: 20260606082412

Contractor: ABC Construction | Location: Plant A
Start: 2026-06-06 08:23:00 | End: 2026-06-06 08:23:00
Requestor: Ayush Krs (ayushkrs2009@gmail.com)

Work Description:
test

Hazards & Control Measures:

TYPE: HOT WORK

#1. Hazard: Fire / Explosion due to flammable materials | PIC: ()

Control Measure: Remove combustibles, maintain fire watch, and keep inspected fire extinguishers nearby

#2. Hazard: Burn injuries from sparks, slag, or hot surfaces | PIC: ()

Control Measure: Wear flame-resistant clothing, gloves, face shield, and proper PPE

#3. Hazard: Toxic fumes and gases inhalation | PIC: ()

Control Measure: Ensure adequate ventilation or local exhaust and use respiratory protection if required

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- HOT WORK ---		
1	Validated that work area is clean of all combustibles	Yes
2	Dedicated Fire Watch with extinguisher is present	Yes
3	Work area has been gas-tested and barricaded	Yes


APPROVED WORK PERMIT

APPROVALS & SIGNATURES

Issuer: Raj Singh (raj.singh.hse@gmail.com)

Time Signed: 2026-06-06 08:53:01


Comments: None



HSE Reviewer: Raj (rksingh988312@gmail.com)

Time Signed: 2026-06-06 08:55:02


Comments: None



Final Approver: raj3 (raj.singh.hse@gmail.com)

Time Signed: 2026-06-06 08:55:24

Comments: None



APPROVED WORK PERMIT

ATTACHED SUPPORTING DOCUMENTS

No attachments were provided for this permit.

APPROVED WORK PERMIT

APPROVED WORK PERMIT & REVALIDATION

DAILY REVALIDATION LOG (OFFLINE)

Date	Shift	Issuer Sign	HSE Sign	Approver Sign