

APPROVED WORK PERMIT

Permit ID: 20260625231903

Contractor: ABC Construction | Location: Plant A
Start: 2026-06-25 23:18:00 | End: 2026-06-25 23:18:00
Requestor: raj (raj.singh.hse@gmail.com)

Work Description:

Hazards & Control Measures:

TYPE: HOT WORK

#1. Hazard: Fire / Explosion due to flammable materials | PIC: ()

Control Measure: Remove combustibles, maintain fire watch, and keep inspected fire extinguishers nearby

#2. Hazard: Burn injuries from sparks, slag, or hot surfaces | PIC: ()

Control Measure: Wear flame-resistant clothing, gloves, face shield, and proper PPE

#3. Hazard: Toxic fumes and gases inhalation | PIC: ()

Control Measure: Ensure adequate ventilation or local exhaust and use respiratory protection if required

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- HOT WORK ---		
1	Validated that work area is clean of all combustibles	Yes
2	Dedicated Fire Watch with extinguisher is present	Yes
3	Work area has been gas-tested and barricaded	Yes

APPROVED WORK PERMIT

APPROVALS & SIGNATURES

Issuer: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-25 23:19:30

Comments: None

HSE Reviewer: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-25 23:25:36

Comments: None

Final Approver: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-25 23:26:20

Comments: None

APPROVED WORK PERMIT

ATTACHED SUPPORTING DOCUMENTS

No attachments were provided for this permit.

APPROVED WORK PERMIT

APPROVED WORK PERMIT & REVALIDATION

DAILY REVALIDATION LOG (OFFLINE)

Date	Shift	Issuer Sign	HSE Sign	Approver Sign