

APPROVED WORK PERMIT

Permit ID: 20260626000317

Contractor: ABC Construction | Location: Zone 5

Start: 2026-06-26 00:02:00 | End: 2026-06-26 00:02:00

Requestor: raj (raj.singh.hse@gmail.com)

Work Description:

cse entry

Hazards & Control Measures:

TYPE: CONFINED SPACE
#1. Hazard: Oxygen deficiency or enrichment PIC: ()
Control Measure: Continuous gas monitoring and maintain oxygen within safe limits (19.5%â23.5%)
#2. Hazard: Exposure to toxic gases (H2S, CO, etc.) PIC: ()
Control Measure: Pre-entry gas testing, forced ventilation, and use of gas detectors
#3. Hazard: Engulfment or entrapment PIC: ()
Control Measure: Isolate all material sources and apply lockout/tagout procedures

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- CONFINED SPACE ---		
1	Confined Space Entry Permit approved by authorized person	Yes
2	Atmosphere tested: Oxygen 19.5%-23.5%, LEL <10%, Toxics within limits	Yes
3	Gas detector calibrated & continuous monitoring arranged	Yes
4	Complete isolation done (mechanical/electrical/pipeline) & LOTO applied	Yes
5	Ventilation provided and space purged/cleaned as required	Yes
6	Entrants, attendant, and supervisor are trained & authorized	Yes
7	Attendant (standby man) deployed at entry point with no other duties	Yes


APPROVED WORK PERMIT

APPROVALS & SIGNATURES

Issuer: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-26 00:05:16


Comments: None



HSE Reviewer: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-26 00:05:41


Comments: None



Final Approver: raj (raj.singh.hse@gmail.com)

Time Signed: 2026-06-26 00:07:48

Comments: None



APPROVED WORK PERMIT

ATTACHED SUPPORTING DOCUMENTS

No attachments were provided for this permit.

APPROVED WORK PERMIT

APPROVED WORK PERMIT & REVALIDATION

DAILY REVALIDATION LOG (OFFLINE)

Date	Shift	Issuer Sign	HSE Sign	Approver Sign