

APPROVED WORK PERMIT

Permit ID: 20260318191309

Contractor: KKSEPL | Location: Plant A

Start: 2026-03-18 19:10:00 | End: 2026-03-18 19:10:00

Requestor: AKASH SHUKLA (akash.shukla@ten.com)

Hazards & Control Measures:

TYPE: CONFINED SPACE

#1. Hazard: Oxygen deficiency or enrichment | PIC: ()

Control Measure: Continuous gas monitoring and maintain oxygen within safe limits (19.5%â23.5%)

#2. Hazard: Exposure to toxic gases (H2S, CO, etc.) | PIC: ()

Control Measure: Pre-entry gas testing, forced ventilation, and use of gas detectors

#3. Hazard: Engulfment or entrapment | PIC: ()

Control Measure: Isolate all material sources and apply lockout/tagout procedures

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- CONFINED SPACE ---		
1	Confined Space Entry Permit approved by authorized person	Yes
2	Atmosphere tested: Oxygen 19.5%-23.5%, LEL <10%, Toxics within limits	Yes
3	Gas detector calibrated & continuous monitoring arranged	Yes
4	Complete isolation done (mechanical/electrical/pipeline) & LOTO applied	Yes
5	Ventilation provided and space purged/cleaned as required	Yes
6	Entrants, attendant, and supervisor are trained & authorized	Yes
7	Attendant (standby man) deployed at entry point with no other duties	Yes


APPROVED WORK PERMIT

APPROVALS & SIGNATURES

Issuer: Raj Singh (raj.singh.hse@gmail.com)

Time Signed: 2026-03-18 19:13:46


Comments: Ensure proper house keeping



HSE Reviewer: Raj (raj.singh.hse@gmail.com)

Time Signed: 2026-03-18 19:14:15

Comments: ensure proper PPEs



Final Approver: raj3 (raj.singh.hse@gmail.com)

Time Signed: 2026-03-18 19:14:52

Comments: approved ensure all hse rules are followed

