Ques-S RCL sch netlist V1 _net0 0 DC 0 SIN(0 0.6 7.5MEG 0 0) AC 0.6 VPr1 net0 vin DC 0 AC 0 L1 vin net1 10U R1.0 vR 30 C1: net1 vR 40P control set filetype=ascii AC LIN 1000 4MEG 12MEG write RCL ac.txt VPr1#branch v(v destroy all TRAN 4.97512e-09 1e-06 0 write RCL tran.txt VPr1#branch v(vIn) v(vR) destroy all

exit -