



NOTE

Over-tightening the screw can cause deformation of the back cover.

