



Importing Inspection Data

QE Data Software — Data Ingestion Tab

PURPOSE — Correctly import a CMM inspection results file (CSV, TXT, or Excel) into QE Data Software's Data Ingestion tab so measured values are captured and checked against tolerance every time.

1 Load the file

Drag your .csv, .txt, or .xlsx report onto the drop zone (or click it to browse). If you pasted text instead, click **Parse Data**.

2 Check the header checkbox

Look at “First row contains column headers” near the top of the mapping screen.

Checked = the file has column titles in row 1 (most CSV exports).

Unchecked = the file starts straight into data, no titles (PC-DMIS's default Excel Report export). The app detects this automatically — you shouldn't need to touch it.

3 Read the status note

A green note means the layout was recognized and Nominal/Actual/Tol+/Tol- are already filled in — skip to Step 5 and just verify.

An amber note means no numeric columns are filled in yet — continue to Step 4.

RECOGNIZED: “Recognized as a standard PC-DMIS Excel Report layout” — Nominal, Actual, and both tolerances are pre-filled. Verify against the sample values, then move on.

NOT RECOGNIZED: “No header row detected” with no further note — map the numeric columns yourself in Step 4.

4 Map the columns by hand (only if the amber note showed with no columns filled in)

Each dropdown option shows a sample value in parentheses, e.g. *Column 4 (3.18)*. Match them using the table below.

Dropdown	Pick the column that has...
Characteristic / Label	the short dimension ID (e.g. LOC2, DIST1) — usually pre-filled already
Nominal	the designed / target value
Actual (measured)	the value the CMM actually measured
Tolerance +	the plus tolerance
Tolerance –	the minus tolerance
Serial Number	the part / unit ID, if present (optional)

5 Link the part

Set “Link results to Part” to the correct part number so tolerances and pass/fail are checked against the master record.

6 Verify the preview

Nominal / Actual / Deviation should show real numbers, not —.

Any row highlighted **red** with **OUT OF SPEC** needs a second look before you save.

7 Save

Click **Save Inspection Run**. If you'll import this same file layout again, click **Save Mapping Profile** first so you never have to remap it.

Questions or a file that won't map correctly? Save the file and flag it to your CMM programmer or quality engineer rather than guessing at tolerance columns.