

## OS Refresh

Inventory - January 2023

 $\rightarrow$  879

workstations at La Ville aux Dames

 $\rightarrow 119$ 

workstations don't run Windows 10

→ 13% of all computers

# Workstations to migrate





## When?

→ 28
FIRST QUARTER

 $\rightarrow$  18 SECOND QUARTER

5

→ UPGRADE IMPOSSIBLE

 $\rightarrow \frac{14}{\text{THIRD QUARTER}}$ 

12

FOURTH QUARTER

6 → UNDER INVESTIGATION



## Upgrade impossible

Hostname <	Service Owne	Fonction/Utilisation	os 🔻	Domaine 🔻	Accès réseau ∨	Date de migratior√	Additional information
VADDSK0372	Production	R&S PG	Windows NT	No	Yes	IMPOSSIBLE	master machine for R&S - finished product test, no more support by supplier since 15 years.
VADDSK0788	SRC	Ligne tachy / radars / AE	Win XP SP3 2600	ad.wabtec.com	Yes	IMPOSSIBLE	need old software for customer services
VADDSK0798	Production	Test final Odo Tachy	WIN XP SP3	ad.wabtec.com	Yes	IMPOSSIBLE	need old software for customer services
VADDSK0823	Production	Testeur R&S PG	Win XP SP3	transp.fr.u3	Yes	IMPOSSIBLE	slave machine for R&S - finished product test, no more support by supplier since 15 years.
VADLAP0935	SRC	Test bench	Win XP	No	No	IMPOSSIBLE	need old software for customer services



#### Investment

16

workstations needs investement

1 154 139 €





### Investment

у -	•			<u> </u>				_		,,,	no I
Hostname↓	Service Owne	os 🖸	Domain	Network acces  ✓	Update date 🕼	Labor (hours) 🗹		Material 🕙	TO	OTAL ☑	Additional information
DIMA-141223001	Production	Win 7	No	Yes	Invest	3200	€	80,000	€	304,000 r	need replacement of the varnish robot
FGUI-10001889	Production	6.7601	ad.wabtec.com	Yes	Invest	700	€	83,939	€	132,939	K-ray tester software/hardware upgrade required
PC 0303	Production	MS DOS	No	No	Invest	2080	€	75,000	€	220,600 \	Wrapping machine, needs to be replaced
PC SEFELEC	Production	Win 98	No	No	Invest 2023	150	€	150,000	€	160,500	Wiring tester that checks the work done by the wrapping machine, needs to be replaced
SPI2	Production	5.00.2195	No	No	Invest	30	€	4,000	€	6,100	Oven for burn-in of cards or finished product, needs to be replaced
SPIRALE-PC	Production	6.1.7600	ad.wabtec.com	Yes	Invest	30	€	4,000	€	6,100	Oven for burn-in of cards or finished product, needs to be replaced
VADDSK1135	Magasin	Win XP	No	No	Invest	150	€	50,000	€	60,500	component programming backup, manufacturing of boards with already programmed components
VADDSK1283	Industrialisation	Win XP	ad.wabtec.com	Yes	Invest						ine 50,291,292 => optical test device for electronic board, manufacturer obsolescence, requires complete thange of the machine
VADDSK1428	Magasin	5.1.2600	ad.wabtec.com	Yes	Invest						Programming of the components, manufacturing of the boards with already programmed components, needs to be replaced
VADDSK2230	Production	6.1.7601	ad.wabtec.com	Yes	Invest BE						
VADDSK2759	Magasin		No	No	Invest					Ł	backup dataio (VADDSK1428), needs to be replaced
VADDSK3540	Production	Win XP	ad.wabtec.com	Yes	Invest 2023	100	€	20,000	€	27,000 r	machine need to be replaced
VADDSK3661	Production	Win XP	No	No	invest	300	€	150,000	€	171 000 L	ine 50,291,292 => optical test device for electronic board, manufacturer obsolescence, requires complete change of the machine
VADDSK3662	Production	Win XP	No	No	invest						ine 50,291,292 => optical test device for electronic board, manufacturer obsolescence, requires complete thange of the machine
VADDSK9411	Production	6.1.7601	ad.wabtec.com	Yes	invest	50	€	15,000	€	18,500 E	Electrical test of the components mounted on the boards - change of boards to be planned
WS-1262	Production	Win XP	faiveleytransport.local	Yes	Invest	120	€	38,500	€	46,900 1	Machine which allows to check that all the micro part of an electronic card is good - needs to be replaced
-											



#### Inventaire.xls

Shared file:

Inventaire.xlsx



