

— LS -10 V — LS -8 V — LS -6 V — LS -4 V — LS -2 V — LS -0.5 V
..... HS -10 V HS -8 V HS -6 V HS -4 V HS -2 V HS -0.5 V

