System Dynamics and Vibrations

Prof. Gustavo Alonso

Chapter 6: Two-degree-of-freedom systems Exercises - 2

School of General Engineering Beihang University (BUAA)

The two-degree-of-freedom system of the figure consists of two masses on a string of tension *T* vibrating in the vertical plane. Let


$$m_1 = m$$


$$m_2 = 2m$$


$$L_1 = L_2 = L$$

$$L_3 = 0.5L$$

Determine the natural modes of vibration







$$m_{1} \frac{d^{2} x_{1}}{dt^{2}} + \left(\frac{T}{L_{1}} + \frac{T}{L_{2}}\right) x_{1} - \frac{T}{L_{2}} x_{2} = F_{1}$$

$$m_2 \frac{d^2 x_2}{dt^2} - \frac{T}{L_2} x_1 + \left(\frac{T}{L_2} + \frac{T}{L_3}\right) x_2 = F_2$$

(with the assumption that displacements are small and being x_i the vibration about the equilibrium position)

$$m_{1} \frac{d^{2}x_{1}}{dt^{2}} + \left(\frac{T}{L_{1}} + \frac{T}{L_{2}}\right)x_{1} - \frac{T}{L_{2}}x_{2} = F_{1}$$

$$m_{2} \frac{d^{2}x_{2}}{dt^{2}} - \frac{T}{L_{2}}x_{1} + \left(\frac{T}{L_{2}} + \frac{T}{L_{3}}\right)x_{2} = F_{2}$$

$$k_{11} = \frac{T}{L_{1}} + \frac{T}{L_{2}} = \frac{2T}{L}$$

$$k_{22} = \frac{T}{L_{2}} + \frac{T}{L_{3}} = \frac{3T}{L}$$

$$k_{12} = -\frac{T}{L_{2}} = -\frac{T}{L}$$

Natural frequencies:

$$\frac{\omega_{1}^{2}}{\omega_{2}^{2}} = \frac{1}{2} \left(\frac{k_{11}}{m_{11}} + \frac{k_{22}}{m_{22}} \right) \mp \frac{1}{2} \sqrt{\left(\frac{k_{11}}{m_{11}} + \frac{k_{22}}{m_{22}} \right)^{2} - 4 \frac{k_{11}k_{22} - k_{12}^{2}}{m_{1}m_{2}}} = \begin{cases} \frac{T}{mL} \\ \frac{5T}{2mL} \end{cases}$$

Mode shapes:


$$\frac{u_{21}}{u_{11}} = -\frac{k_{11} - \omega_1^2 m_1}{k_{12}} = -\frac{\frac{2T}{L} - \frac{T}{mL} m}{\frac{T}{L}} = 1$$

$$\frac{u_{22}}{u_{12}} = -\frac{k_{11} - \omega_2^2 m_1}{k_{12}} = -\frac{\frac{2T}{L} - \frac{5T}{2mL}m}{\frac{T}{L}} = -0.5$$

Normalization of modal vectors: $u_{11} = 1$, $u_{12} = 1$


$$\mathbf{u}_1 = \begin{bmatrix} u_{11} \\ u_{21} \end{bmatrix} = \begin{bmatrix} 1 \\ 1 \end{bmatrix}, \mathbf{u}_2 = \begin{bmatrix} u_{12} \\ u_{22} \end{bmatrix} = \begin{bmatrix} 1 \\ -0.5 \end{bmatrix}$$


$$\mathbf{u}_1 = \begin{bmatrix} u_{11} \\ u_{21} \end{bmatrix} = \begin{bmatrix} 1 \\ 1 \end{bmatrix}, \mathbf{u}_2 = \begin{bmatrix} u_{12} \\ u_{22} \end{bmatrix} = \begin{bmatrix} 1 \\ -0.5 \end{bmatrix}$$



$$\omega_1 = \sqrt{\frac{T}{mL}}$$

$$\boxed{5T}$$





Consider the model shown in the figure. Let the parameters have the values:

m = 1,500 kg

 $I_C = 2,000 \text{ kg} \cdot \text{m}^2$


 $k_1 = 36,000 \text{ kg/m}$


 $k_2 = 40,000 \text{ kg/m}$

a = 1.3 m

b = 1.7 m

Calculate the natural modes of the system and write an expression for the response





$$m\ddot{x} + (k_1 + k_2)x - (k_1a - k_2b)\theta = 0$$
$$I_C \ddot{\theta} - (k_1a - k_2b)x + (k_1a^2 - k_2b^2) = 0$$

Equations of motion:
$$m\ddot{x} + (k_1 + k_2)x - (k_1a - k_2b)\theta = 0$$

$$I_C\ddot{\theta} - (k_1a - k_2b)x + (k_1a^2 - k_2b^2) = 0$$

$$\begin{bmatrix} 1,500 & 0 \\ 0 & 2,000 \end{bmatrix} \begin{bmatrix} \ddot{x} \\ \ddot{\theta} \end{bmatrix} + \begin{bmatrix} 76,000 & 21,200 \\ 21,200 & 176,440 \end{bmatrix} \begin{bmatrix} x \\ \theta \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \end{bmatrix}$$

Solution (harmonic):

$$x(t) = X \cos(\omega t - \phi), \quad \theta(t) = \Theta \cos(\omega t - \phi)$$

Eigenvalue problem:

$$-\omega^{2} \begin{bmatrix} 1,500 & 0 \\ 0 & 2,000 \end{bmatrix} \begin{bmatrix} X \\ \Theta \end{bmatrix} + \begin{bmatrix} 76,000 & 21,200 \\ 21,200 & 176,440 \end{bmatrix} \begin{bmatrix} X \\ \Theta \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \end{bmatrix}$$

Natural frequencies (solve the characteristic equation):

$$\det\begin{bmatrix} 76,000 - 1,500\omega^2 & 21,200 \\ 21,200 & 176,440 - 2,000\omega^2 \end{bmatrix} = 0 \longrightarrow \frac{\omega_1^2}{\omega_2^2} = \begin{cases} 47 \text{ (rad/s)}^2 \\ 91 \text{ (rad/s)}^2 \end{cases}$$

Natural modes:

$$-\omega^{2} \begin{bmatrix} 1,500 & 0 \\ 0 & 2,000 \end{bmatrix} \begin{bmatrix} X \\ \Theta \end{bmatrix} + \begin{bmatrix} 76,000 & 21,200 \\ 21,200 & 176,440 \end{bmatrix} \begin{bmatrix} X \\ \Theta \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \end{bmatrix}$$

$$\omega^2 = \omega_1^2 \implies \frac{\Theta_1}{X_1} = -0,257 \text{ rad/m}$$

$$\omega^2 = \omega_2^2 \implies \frac{\Theta_2}{X_2} = 2,914 \text{ rad/m}$$

$$X_1 = 1, X_2 = 1$$
 \Rightarrow $u_1 = \begin{bmatrix} X_1 \\ \Theta_1 \end{bmatrix} = \begin{bmatrix} 1 \\ -0.257 \end{bmatrix}, u_2 = \begin{bmatrix} X_2 \\ \Theta_2 \end{bmatrix} = \begin{bmatrix} 1 \\ 2.914 \end{bmatrix}$

Natural modes:

$$\omega_1 = 6.83 \text{rad/s}$$

$$\omega_2 = 9.18 \text{rad/s}$$

