-90 PSM 1, Joint 1	-45			0 PSM 1,	Joint 1	45		
-135 PSM 1, Joint 2 -90			-45 P	SM 1, Joint 2	0			
-90 PSM 1, Joint 3	5	0 PSM 1,		45			135	
135 PSM 1, Joint 4 90		45	0	PSM 1, Joint 4	-45		-90	-135
-135 PSM 1, Joint 5 -90		-45	0 PSI	M 1, Joint 5	45	90	135	5

90

This box should be 20 cm long if printed correctly